

4th year maintenance Bill

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
M/W.	Gariarozan Se Bogomatti Bondhi				
	via Kalyanpur Boudh talu under				
	Muzasy sub. Aurai Block.				
Agency	Vijay Kumar Roushan				
Agreement NO.	Muzasy/250/29/2018-19				
Actual date of completion	25/8/2019				
	Detailed m/s				
①	Restoration of Ravals work				
	2010 - all complete job				
	for 814 of P.L.				
	12	3.60	1.25	0.30	16.20 M ³
	14	4.50	1.30	0.40	32.76 "
	12	3.75	1.10	0.30	21.04 "
	10	4.10	1.00	0.40	16.40 "

	5	4.40	1.30	0.30	7.80 "
	11	3.50	1.40	0.30	16.17 "
	13	5.00	1.05	0.35	23.89 "
	8	3.00	0.95	0.30	6.84 "
	15	5.50	1.00	0.30	24.75 "
	10	3.50	1.05	0.30	11.03 "
	17	2.50	0.95	0.30	12.11 "
	12	3.50	1.15	0.30	14.49 "
	11	4.10	1.20	0.30	15.84 "
					= 219.32
					M ³

②	Maintenance of E/shoulder				
	by adding selected soil				
	all complete job				
	2	5	30.00	1.20	360 M ²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(10)					R 3390612
	=	484.99 m ²	2.21 / m ²		R 10700
(11)					R 113721
					R 3412680
					R 341272
					R 3071412

20/5/2024
 08

MATERIAL STATEMENT

(1)	Earth	219.32 m ³
(2)	Gravel	37.57 m ³
(3)	Sand	7.45 m ³
(4)	Portland Cement	0.35 MT
(5)	Portland Cement	0.056 MT
(6)	Portland Cement	0.39 MT

20/5/2024
 12