

5th year maint. 106/1

65

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Sarpol Taxia					
P.O. Chaturanga Mazaffarpur					
Sdalsar ser. - Lar Bhowan					
Khanpali 2e 10 2000					
Polsam ke phors 10000					
Dighra Talb.					

Agency - Umesh Rai
 Ag. no - 13/SBP/MM/65/1879
 Actual dt. of comp - 15/4/19
 Dt. of measmt - 10/1/23

1) Restoration of wall
 mts.

10 x 30 x 0.90 x 0.30	87.0
2 x 4 x 12.5 x 0.8 x 0.3	24.0
5 x 9.5 x 0.75 x 0.30	10.74
	115.73
	m ³

2) maintenance of east
 shoulder

2 x 9 x 30 x 0 x 1.0	540.0
3 x 30 x 0.90	81.0
24.50 x 0.90	22.05
	643.05
Limit -	642.54
	m ²

Continuation

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(13) white washing of					
parapet					
23.81 m ² side to D.P.O. (67)					
(2) 15.65 m ²					373 =
					<u>1757912</u>
1.85 107. res. parapet					221286
					<u>22126 =</u>
					<u>199138 =</u>
Quota 7.04.24					
Quota 7.04.24 DE					
					<u>10/5/24</u>