

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
5th year of maintenance work					
Name of Road → Hathaur Bazar					
road road & name of Upendras					
chandhari is Kala Block.					
Name of Contractor → Bipesh Kumar					
Agreement No → MMBSY/ SBD/91					
2018/19					
Date of work order → 31/7/2018					
Date of Completion → 2/1/19					
① Restoration of rain cuts					
with soil, moorum gravel					
on a mixture of these at					
do all work					
1	4.12	1.15	0.30		21.42 m ³
2	5.61	1.28	0.30		4.30 m ³
3	4.29	1.39	0.30		5.36
2	5.85	1.31	0.30		4.59 m ³
					15.67 m ³
② Making up loss of material					
irregularity on shoulder to					
the design level by adding					
fresh approved material					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑤ Cutting of Branches of tree and Shrub from the road etc do all contents					
2 No Circle Tomb - 28					
⑥ Toronomy of grass and weeds from the Shoulders etc do all etc					2142m
96.90 m ² (1 No. Tomb - 28					
③ 2221 m ² - 1					2142m
					16303m
less 10% delo - 0					16302m
					1467320
21 2812123					
513					
Material station					
① Soil (Bank) -					15.67m
22 2812123					
513					