

575118

Schedule X V-Form No. 134

1038 to Karamcupa & Jin.

Mithlesh Kumar.

E. E. ~~Arav D~~ Ragsoudh

DIVISION

Govindpur.

SUB-DIVISION

MEASUREMENT BOOK

M.B.No-

836

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Const / Maintenance of Red form work TO Kumbhar die under GTSKY,					
Agency - Mithlesh Karm					
Ref No 40/SBD/GTSKY/201879					
Date of completion - 13/04/2019					
① Restoration of gain up with S/L :-					
2x	20.4x	1.30x	0.30	15.60m ²	
3x	20.4x	1.10x	0.30	19.80m ²	
4x	15.4x	1.25x	0.30	22.50m ²	
3x	10.4x	1.20x	0.30	9.60m ²	
					26.70m ²
② Maintenance of earthen shoulder -					
4x	30.4x	1.10x		132.40m ²	
2x	30.4x	1.15x		46.00m ²	
3x	30.4x	1.20x		90.00m ²	
					268.00m ²
③ Trimming of grass and weeds from shoulder					
3x	30.4x	1.20x		108.00m ²	
2x	30.4x	1.15x		69.00m ²	
1x	25.4x	1.05x		26.25m ²	
					203.25m ²

For 15.04.2019 Continuation

ABSTRACT of cut

38

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of main cut mk 501 —					
66.70 m (GMBP 37)					
Ct 348 16/12/14					23292.4
(2) Maintenance of channel.					
268.10 m (GMBP 37)					
Ct 52.09/14					13960.4
(3) Formation of 90m x 4 m from shoulder					
203.25 m (GMBP 37)					
Ct 2.08/14					423.4
					37675.4
100 m of 80 ft to 100 ft					3767.4
					33907.0
For 15.04.14					
TE					
For 20/11/22					
A.E.					
Maintenance of channel					
(1) Ent. 66.70 m					
For 15.04.14					
For 20/11/22					
A.E.					