

Suseet Kumar

15/03/22-23 अधिकृत पट्टेदार द्वारा
Schedule XLV Form No.-134
BIHAR P.W.D.

(313<810) अंग्रेजी
(111633-50)

31<16

DIVISION

3133

SUB-DIVISION

MEASUREMENT BOOK

श्री अमरनाथ झा द्वारा मापने के लिए
31310 31310

2nd ^{Year} ~~on A~~ Maintenance

Sch. XLV-Form No.134

6

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Maintenance of road from Mathiya Paschim Tola to Miya Tola under Ministry					
Agency - Sujit Kumar					
Agreement No - 20 SBD/2020-21					
Actual date of completion - 10/08/2021					
2nd Year Maintenance Period 11/08/2022 to 10/08/2023					
① Restoration of rainwater					
2	X	6.40	X	1.10	X 0.25 = 3.30 m ³
2	X	7.40	X	1.20	X 0.25 = 4.20 m ³
1	X	2.15	X	1.15	X 0.30 = 2.81 m ³

	2	V	6.50	X 1.20	X 0.25 = 3.90 m ³
	2	X	7.40	X 1.25	X 0.30 = 5.25 m ³
	1	X	6.40	X 1.20	X 0.25 = 1.80 m ³
					21.26 m ³

SMU
01/08/23
JE

② Maintenance of earthen shoulder					
	1	X	7.10	X 1.20	= 8.52 m ²
	2	X	9.50	X 1.15	= 21.85 m ²
	3	X	11.50	X 1.28	= 44.16 m ²
	2	X	8.40	X 1.20	= 19.20 m ²
	3	X	7.50	X 1.25	= 28.12 m ²
	4	X	9.40	X 1.20	= 43.20 m ²
	2	X	6.50	X 0.90	= 11.70 m ²
	5	X	6.75	X 1.25	= 42.19 m ²



Continuation

218.94 m²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(3) Maintenance of Bituminous					
— surface road					
Patch repair:					
1	X	2.50	X	1.25 =	3.12 ² ft
1	X	3.00	X	1.50 =	4.50 ² ft
2	X	3.25	X	1.50 =	0.73 ² ft
1	X	2.00	X	1.20 =	2.40 ² ft
2	X	3.50	X	0.80 =	5.60 ² ft
					16.35 ² ft
(4) Maintenance of Slab					
culvert ———					1 May
(5) Cutting of boundary					
of Trees ———					1 May
(6) Maintenance of trees					
by branch the road side					36 May
(7) Maintenance of earthen					
— shoulder					
2	X	6.50	X	1.10 =	14.30 ² ft
3	X	7.10	X	1.10 =	23.43 ² ft
2	X	8.00	X	1.20 =	19.20 ² ft
3	X	9.00	X	1.20 =	32.40 ² ft
2	X	7.00	X	1.15 =	16.10 ² ft
2	X	6.00	X	1.25 =	15.60 ² ft
4	X	9.50	X	1.15 =	43.70 ² ft
1	X	7.10	X	0.90 =	6.39 ² ft
2	X	6.00	X	1.10 =	13.20 ² ft
3	X	8.15	X	1.20 =	29.34 ² ft
Continuation					213.66 ² ft

SMU
03/08/2023
JE

05/09/23
PSE

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(i) Maintenance of road sign					1.13 Km
(ii) Maintenance of 250m stone					2.25 Km
(8) Trimming of grass					
2 X 10 X 30 X 0.65					390.20 m ²
(9) Maintenance of earthen shoulder					
2 X 6.50 X 0.80					10.40 m ²
2 X 8.00 X 1.28					20.48 m ²
2 X 6.00 X 1.25					15.00 m ²
2 X 7.00 X 1.28					21.28 m ²
2 X 11.00 X 1.25					27.50 m ²
4 X 8.50 X 1.15					39.10 m ²
3 X 9.50 X 1.10					31.35 m ²
2 X 7.00 X 1.25					21.25 m ²
2 X 8.75 X 1.15					20.12 m ²
3 X 9.00 X 1.20					32.40 m ²
3 X 7.00 X 1.10					23.10 m ²
2 X 8.00 X 1.20					19.20 m ²
1 X 9.50 X 1.25					11.87 m ²
3 X 6.50 X 1.20					23.40 m ²
					326.42 m ²
 S. E. 05/08/2023  05/08/23 PB					

Continuation

Abstract of cast

9

Sch. XLV-Form No.134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Kaincent					
Q-V77B/6 ① = 21.26 m					
e h 406 = 82/11 m					864920
② Maintenance of earthen shoulder					
Q-V77B/6 ② = 218.94 m					
P7 ② = 213.66 m					
P8 ② = 326.42 m					
759.02 m					
e h 61 = 70/11 m					4683220
③ Maintenance of bitumen surface road					
Q-V77B/7 ③ = 16.35 m					
e h 304 = 51/11 m					497720
④ Maintenance of slab e evert					
Q-V77B/7 ④ = 1 Na					
e h 2329.21/each h					232920
⑤ cutting of branches of trees					
Q-V77B/7 ⑤ = 1 Na					
e h 109 = 74/each h					11020
⑥ Trimming of grass					
Q-V77B/8 ⑥ = 390.00 m					
e h 2.24/11 m					87420

Continuation

63,77320

Continuation