# कार्यपालक अभियंता का कार्यालय, ग्रामीण कार्य विभाग, कार्य प्रमण्डल, रजौली।

Mob No.: 8986915851.

Email I.D.: - eerwdrajauli@gmail.com

पत्रांक....६.२.६/.३५.वु.ः..

रजीली / दिनांक. २२.२.० इ. । १६

प्रेषक.

ई0 अरविन्द कुमार, कार्यपालक अभियंता।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव, बिहार ग्रामीण पथ विकास अभिकरण, पटना।

विषय :-MMGSY [NDB-Bricks] योजनान्तर्गत आवंटित राशि का उपयोगिता प्रमाण पत्र तथा आवंटन अधियाचना के संबंध में |

महाशय,

उपर्युक्त विषयक एवं प्रासंगिक पत्र के संबंध में कहना है,इस प्रमंडल के अधीन MMGSY [NDB-Bricks] योजनान्तर्गत चल रहे कार्यों के भुगतान हेतु आवंटन की माँग विहित प्रपत्र मेंs उपयोगिता प्रमाण पत्र संलग्न करते हुए आग्रह है,कि आवंटन उपलब्ध करने की कृपा की जाय ताकि कराये गए कार्यों का भुगतान किया जा सकें।

अनु0- यथोक्त|

विश्वाशभाजन,

कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमंडल, रजौली।

Scanned with CamScanner

Rural Works Department,

Works Division Rajauli, Requisition of Allotment under MMGSY NDB (BRICKS) Fund,

Name of the Division :- RWD (W) Division Rajauli.

			-4	-	No.		
	Amount. (Rupees Forty Nine Lakh Thirty One Thousand One Hundred Twenty Three only)		1050270190008		Project ID		
			NH 31 To Damodarpur	w	Name of the Road		
			0.600	4	Road Length (In Km.)		
			83.95000	5	AA Amount (in Lakh)		
			03/MMGSY- NDB/Bricks/SBD/ 2023-24	6	Agreement No.		
			MMGSY-NDB- BRRP-409- Rajauli	7	Package No.		
			Bipin Buildtech Private Limited	æ	Name of the Contractor		
		76.49522	76.49522	9	Estima Agreeme La Main Work (in Lakh)		
		2.24309	2.24309	10	Estimated Cost Agreement Value (In Lakhs)  Nork Naintenance Nork Nork (in Lakh) Lakh)		
	irty One Tho	78.73831	78.73831	11	Agreement Amount		
	usand One Hu		18.08.2023	12	Fund Fund Date of Received Expenses Completion till date (in till Date (In Lakhs)		
	ndred Twent		23.59468	13	Fund Received till date (in Lakh)		
	/ Three only)	23.59468	23.59468	14			
		23.59468 72.90591	23.59468 23.59468 72.90591	15	Value of Measuremen t (In Lakhs)		
		49.31123	49.31123	Value of Current Measuremen Demand (In Remarks t (In Lakhs) Lakh)  15 16 17			
12			Completed	17	Remarks		
			_	_	7.		

Executive Engineer,
Rural Works Department,
Works Division Rajauli.

Scanned with CamScanner

#### FORM GFR 19-A

(See Government of India's Decision (1) below Rule 150) Form of Utilization Certificate up to the Month of 18-MAY-2024.

## MMGSY [NDB-Bricks]

S. No	Name of Scheme	Sanction No. & Date with Amount (In Rs.lacs)	Amount Received (in Rs.Lacs)	Decrese (in Lacs)	Particulars
7	MMGSY NDB Bricks	As on 31-MARCH-2023 Lt. 140 Dt. 16.10.23 Lt. 177 Dt. 14.12.23 Lt. 151 Dt. 05.01.24 Lt. 216 Dt. 29.02.24 Lt. 219 Dt. 07.03.24 Lt. 226 Dt. 19.03.24 Lt. 239 Dt. 23.03.24 Lt. 248 Dt. 30.03.24 Lt. 18 Dt. 18.05.24	78.20483 89.55481 127.42663 41.80824 47.79618 202.23835 72.65080 23.59468 16.37313		Certified that out of Rs. 699.64765 Lakh received during the Financial Year 2024-25 (18-MAY-24) in favour of Executive Engineer,RWD (W) Divsion, Rajauli, Bihar out of which a sum of Rs. 699.63973 Lakh Lacs has been utilized for the purpose of MMGSY [NDB-Bricks] Scheme as given in the margin for which it was sanctioned and Rs. 0.00000 has been surrendred and that the balance of Rs. 0.00792 Lacs remaining unutilized at the end of the said period.
			699.64765	0.00000	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

### Kind of Checks exercised :-

- (i) Works have been supervised by Executive Engineers/Superintending Engineer.
- (ii) Periodic inspection has been conducted by Executive Engineer/Superintending Engineer.
- (iii) Construction materials have been tested.
- (iv) Measurements have been recorded in the MBs and test check conducted by the Assistant.
- (v) All other codal formalities have been observed.

# Physical Progress achieved :-

- (i) Construction of Road Works
- (ii) Construction of CD Works

Executive Engineer, Rural Works Department, Works Division, Rajauli.

Scanned with CamScanner