

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(14) Maint ⁿ of culverts — do —					01 Nos.
(15) Maint ⁿ of road sign — do —					0.2 km
(16) Maint ⁿ of 200m diamond stone — do —					0.2 km
(17) Cutting of branches — do —					2 Nos.
(18) Cutting of shrubs — do —					9 Nos.
(19) Trimming of grasses — do —					
					2x1x3 @
					2x 20.20 x 1.0 = 40.4 m ²
Abstract					
20.123					20.123
20.123					20.123
20.123					20.123
1st year Maint ⁿ Abstract					
(10) Restoration of rain cul —					
— all as per TIS and inst ⁿ of					
E. ie					
Qty = 56.09 m ³ UTM B 434					
Unit @ 50.63 m ³ @ 380.58 / m ³ = 19267-					
(10) Maint ⁿ of earthen shoulder —					
— do —					
Qty = 264 m ² UTM B 434					
Unit @ 239.16 / m ² @ 58.37 / m ² = 13959-					
(10) Maint ⁿ of bitumen surface —					
— for repair — do —					
Qty = 18.72 m ² UTM B 434					
@ 347.54 / m ² = 6506:-					

Continuation

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>21. General Maintenance Measurement</u>					
(21) Restoration of rain cut - all as per the order of the					
	16	3.25	1.0	0.2	10.403
	8	3.50	1.0	0.2	5.60
	4	5.20	1.0	0.2	4.16
	15	4.70	1.1	0.2	15.51
	16	4.2	1.0	0.20	13.44
	8	6.5	1.05	0.2	10.92
				Total:	60.03m ³
(22) Maintenance of earth shoulders					
	2	8	20.0	1.0	896m ³
(23) Patch repair - B repair					
	16	1.2	0.9		17.28
	3	1.50	1.40		6.30
	1	1.92	1.80		2.46
	6	0.9	0.90		4.86
	4	1.2	1.05		5.04
				Total:	36.94m ³
(24) Maintenance of culverts - old					
				01 Nos.	
(25) Maintenance of Road sign - 6					
(26) Maintenance of road lamp post - 2 Nos.					
(27) Cutting of branches - 2 Nos.					
(28) Cutting of shrubs - 10 Nos.					

Continuation

Continuation

Scanned with OKEN Scanner

