

Abstract of cost

69

Sch. XLV-Form No. 134

Particulars.	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2nd year Maint. Bill					10.38
Name of work - Maint. of Road					
to S to Dangdaga Dar					
Total					
Agency - Parasheth Const.					
Purnea.					
Agreement No - 46 STD/2018-19					
Actual Dt. of completion - 23/12/2019					
1/15.1 Restoration of rain					
cut with soil					
Qty vide T.M.B.					
P					
133.19 M ³ @ 380.58/M ³					
⇒ 50,689 = 45					
2/15.2 Making up of Berms					
Shoulder, stopping					
of excess earth					
Qty vide T.M.B. - (68)					
742.03 M ² @ 58.60/M ²					
⇒ 43,482 = 29					
3/15.3 (iv) P/L Restumens					
Surface with 20mm					
prime carpet					
with soil east					
Qty vide T.M.B. - (68)					
60.78/M ² @ 335.79/M ²					

Continuation.

$$\Rightarrow 20,409232$$

1,14,581273

178.22

Continuation