

2nd year maintenance

59

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No	L	B	D	
Name of Work: Mahua Meishder					
Row: Keshor to Choudharshi					
Agency: - Manjeet Kumar.					
Agreement No - 11/M/MSY/886/					
					2020-21.
Date of work order -					04/06/2020.
Date of completion -					31/6/2021.
Actual Completion -					23/02/2022.

Revised Measurement

Item 1. Restoration of Boundary

Beam with 80/1. Compf job.

$$10 \times 8.10 \times 1.10 \times 0.3 = 26.73$$

$$14 \times 8.50 \times 1.00 \times 0.30 = 10.20$$

$$8 \times 6.30 \times 1.05 \times 0.30 = 15.12$$

$$12 \times 4.70 \times 1.05 \times 0.30 = 5.92$$

$$3 \times 10.50 \times 1.10 \times 0.30 = 10.39$$

$$10 \times 2.90 \times 1.00 \times 0.30 = 4.35$$

$$= 72.71 \text{ m}^3$$

Item 2. Marking up 4 Beam

Shoulder & trapezium

Excess 80/21. Compf

job.

$$8 \times 5.20 \times 1.10 = 45.76$$

$$7 \times 4.50 \times 1.10 = 34.65$$

$$6 \times 6.30 \times 1.0 = 37.80$$

$$5 \times 7.30 \times 1.08 = 38.32$$

Continuation



Abstract of cost

63

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Raincuffs					
Qty mds of m B.P. (59)					
72.71 m ² @ Rs 386.14/m ² B.P.					28076-w
② Making up of Berms/Shoulder					
Qty mds of m B.P. (59)					
269.82 m ² @ Rs 57.36/m ² B.P.					15477-w
③ Repair of pot holes					
④ Bitumen mcs					
⑤ Repair of pot holes with Bitumen mcs.					
Qty mds of m B.P. (60)					
37.39 m ² @ Rs 296.86/m ² B.P.					11099-w
⑥ Maintenance of H.P. Culvert					
Qty mds of m B.P. (60)					
9 nos @ Rs 1130.67/each					2261-w
⑦ Maintenance of 5' slab Culvert					
Qty mds of m B.P. (60)					
1 no @ Rs 2329.20/each					2329-w
⑧ Maintenance of Road Sign					
Qty mds of m B.P. (61)					
0.14 km @ Rs 1077.89/km					155-w
⑨ Maintenance of km and 2mm stone					
Qty mds of m B.P. (61)					
0.18 km @ Rs 628.23/km					113-w

Continuation



