

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4th year Maintenance					
Name of Work - Maintenance of 2nd from PMGSY Ladhak					
KE Sinwan more to Nathu					
bigha Under mmGJY (SC)					
Agent - m/s Singh Consult					
Agreement no - SRS/ 2018-1					
Actual Date of completion -					
05/08/2019					
Date of Entry - 12/01/2019					

## ① Restoration of rainforest-

with soil

$$2 \times 4 \times 30.8m \times 0.9m \times 0.3m = 64.80 m^3$$

$$2 \times 8.50\text{ m} \times 1.0\text{ m} \times 0.3\text{ m} = 27.0\text{ m}^3$$

$$2 \times 30.0\text{m} \times 0.80\text{m} \times 0.3\text{m} = 14.4\text{m}^3$$

$$2 \times 9.4\text{m} \times 0.95\text{m} \times 1.3\text{m} = 51.3$$

$2 \times 2.10 \text{ cm} \times 0.80 \text{ cm} \times 0.3 \text{ m} = 1.10$

90.43 in

## ② Making up of Bony Shoulder

$$2x^4 \times 30.4 \text{ fm}^x \times 1.0 \text{ fm} = 240.4 \text{ fm}^2$$

$$2 \times 4 \times 30.4 \text{ m} \times 0.75 \text{ m} = 180.4 \text{ m}^2$$

$$2 \times (30 + 17.0) \times 0.90 = 84.60m^3$$

504.60m<sup>2</sup>

### ③ Repair of pot holes

followed with observations

$$19.60 \text{ m} \times 1.70 \text{ max } 0.075 \text{ m} = 2.58 \text{ m}^3$$

Sch. XLV—Form No. 134