

2nd year Maintenance

52

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work—					
Mathiya					
Path to Mathiya Hariton Tola.					
Authority—					
E. E. RWD					
Bagaha—					
1.					
Agency—					
Pawan Kumar					
Verma.					
Agg. no—					
45 SBD/2019-20.					
Date of start—					
11/9/2019.					
Date of comp—					
10/6/2020.					
AIDIC—					
7/01/2022.					

① Restoration of rain
cuts with soil—

$$25 \times 2.80m \times 1.50 \times 0.30 = 31.50m^3$$

$$8 \times 3.10m \times 1.80 \times 0.30 = 13.39m^3$$

$$= 44.89m^3$$

② Maint of earthen
shoulder with soil—

$$12 \times 8.10 \times 1.00 = 97.20m^2$$

③ Patch repair on
bituminous surface—

$$6 \times 1.60 \times 1.10 = 10.56m^2$$

④ Maint. of R.C.C. culvert—

$$1 \times 1nos. = 1nos.$$

⑤ Maint. of road signs—

$$1 \times 1.20km = 1.20km$$

⑥ Cutting of branches
of trees—

Continuation

Continuation