

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd Year Maint. Bill					
Name of the work —					
PMGSY Telpur to					
Inarbarwa Letiya.					
Authority — E. E. RWD.					
Bagaha-1.					
Agency — Rajan Kumar.					
Agg. no — 17 SBD/2019-20					
D/S — 30/7/2019					
D/C — 29/7/2020.					
A/D/C — 30/8/2020.					

① Restoration of rain cuts with soil —

~~100 x 3~~

$$16 \times 2.50 \times 1.80 \times 0.30 = 21.60 \text{ m}^3$$

$$32 \times 2.30 \times 1.75 \times 0.30 = 38.64 \text{ m}^3$$

$$56 \times 2.60 \times 1.85 \times 0.30 = 80.81 \text{ m}^3$$

$$30 \times 2.00 \times 1.50 \times 0.30 = 27.00 \text{ m}^3$$

$$= 168.05 \text{ m}^3$$

② Maintenance of embankment

Shoulder with soil —

$$22 \times 16.50 \times 1.12 = 406.56 \text{ m}^2$$

$$19 \times 8.80 \times 1.10 = 183.92 \text{ m}^2$$

$$= 590.48 \text{ m}^2$$

③

Continuation

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Qty. wide p.m. - (91) of TMB.					
14.50 m ² @ 16.65					
					= 241.00
					= 449.701 = 00
Less 0.11% Below = (-) 495 = 00					
					= 449.206 = 00
Summed 29/8/23 J.E.					= 654133 = 00
Less 0.11% Below = (-) 720 = 00					
					= 653413 = 00
Reviewed & signed 29/08/23 J.E.					