

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	

Name of Road :- R-E-O path to

Tinaj M Goyal Se

Agency :- Mr. Parman Singh

Agreement No :- 28580 of 2020-21

Date of start - 1 - 01-05-2020

Date of completion 1-28-02-2021

① Restoration of Pavements /

Berm width 80 ft

$$15 \times 2.50 \times 1.25 \times 0.300 = 14.06 m^3$$

$$20 \times 1.50 \times 1.25 \times 0.350 = 13.12 m^3$$

$$7 \times 2.00 \times 1.95 \times 0.300 = 5.25 m^3$$

$$32.43 m^3$$

② Making up of shoulders

shoulder

$$30 \times 1.9 \times 1.25 \Rightarrow 41.25 m^2$$

$$25 \times 1.40 \times 1.25 \Rightarrow 43.75 m^2$$

$$40 \times 2.00 \times 1.25 \Rightarrow 100.00 m^2$$

$$215.00 m^2$$

③ Patch repair over 11 turns

surface with 20 mm premix

compt

Continuation

Sch. XLV-Form No. 134

~~Rs 128 = 27480.00~~

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Maintenance of road					
Simp —					
TFCP —	68	QH — 0.08 KIT			
(2) 105.4-281 KIT \Rightarrow 84.00					
(3) Maintenance of road					
280m stone —					
TFCP —	68	QH — 0.09 KIT			
(3) 261.091 KIT \Rightarrow 51.00					
(4) cutting of branches					
of tree —					
TFCP —	68	QH — 2.00 NO			
(4) 106.081 NO \Rightarrow 212.00					
					24824.00
(5) Legs 0.01% below					\Rightarrow 2.7800
					24824.00

~~✓ 3-2022~~
~~✓ 3-2022~~
JE

Material statement

E/ wood - 32-4.3 m ³		

✓ 3-2022	C&P	
DE		
		08: 08.12

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road :- P. E. O Path to Ji-osi -					
Agency :- Govt Pamm Singh					
Agreement No 2 - 229901 2020-21					
Date of start :- 01-03-20					
Date of completion - 08-02-21					
① Restoration of pavements dimensions -					
$15 \times 3.5 \times 1.25 \times 0.300 \Rightarrow 19.68 m^3$					
$16 \times 5.00 \times 1.25 \times 0.300 \Rightarrow 24.00 m^3$					
$18.25 m^3$ $38.49 m^3$					
② Making up of 30m ² shoulders -					
$32 \times 1.800 \times 1.25 \Rightarrow 72.00 m^2$					
$22 \times 2.000 \times 1.25 \Rightarrow 55.00 m^2$					
$19 \times 5.50 \times 1.25 \Rightarrow 130.63 m^2$					
$257.63 m^2$					
③ Patch repair areas dimensions dimensions carpet -					
$10 \times 1.50 \times 1.25 \Rightarrow 18.75 m^2$					
$8 \times 1.100 \times 1.25 \Rightarrow 11.00 m^2$					
$29.75 m^2$					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Work:- R. E.O Path to Tisasi					
Agency:- Giri Ramon Singh					
Agreement no:- 28(SBD) / 2020 - 21					
Date of start:- 31/05/20					
Date of completion:- 28/01/2021					
Item no(1) Restoration of burnt cuts /					
Dimensions --- G.C					
10 x 7.00 x 0.90 x 0.300 = 18.90 m ³					
5 x 6.00 x 0.80 x 0.300 = 7.20 m ³					
5 x 5.00 x 0.90 x 0.300 = 6.75 m ³					
10 x 6.00 x 0.80 x 0.300 = 14.40 m ³					
				= 47.24 m ³	
					m ³
					Count = 46.07

Item no(2) making up of excess soil /					
Dimensions --- G.C					
10 x 2.00 x 1.00 = 20.00 m ²					
5 x 5.00 x 1.00 = 25.00 m ²					
1 x 4.00 x 1.00 = 4.00 m ²					
9 x 3.00 x 0.80 = 21.60 m ²					
10 x 10.00 x 0.90 = 90.00 m ²					
10 x 10.00 x 0.90 = 90.00 m ²					
20 x 2.00 x 1.00 = 40.00 m ²					
					= 301.00 m ²

