

Sch. XLV-Form No. 134

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	
1st on A/c Bill				
1st year maintenance				
Name of work —				
Loos to Haripur to La.				
Authority- E.C.R.W.D.				
Dalsingh sarai.				
Agency- walls Infrastructure Co.				
Agg. No- 01 SBD/2018-2019				
Date of start- 25/6/18				
Date of comp- 24/6/19				
A. date of comp- 20/6/19.				
Work done —				
Record Measurement —				
① Restoration of rain cuts with soil —				
$112 \times 1.70 \times 1.58 \times 0.30 = 90.25 m^3$				
$38 \times 1.56 \times 1.35 \times 0.3 = 24 m^3$				
$= 114.26 m^3$				
② Maint. of earthen shoulder with soil —				
$62 \times 5.5 \times 1.42 = 484.22 m^2$				
$25 \times 4.70 \times 1.30 = 152.75 m^2$				
$= 636.97 m^2$				
③ Main. of H.P. culvert —				
$2 \times 8 nos. = 16 nos.$				

Continuation

