

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4th Year Maintenance					
Name of work	1.	Loos to Bech Jola.			
Audhonds		CE R.W.D			
		Dalsingh Street			
Agg. No.	02630/	2018-19			
Date of Start	25.05.2018				
Date of Completion	24/06/2019				
M.D.C.	21/06/2019				
Work done					

① Pl Restoration of Rain

Cuts	5m				
5916	$2.100 \times 1.25 \times 0.300$				52.33 m ³
4540	$2.00 \times 1.800 \times 0.300$				48.600 m ³
4540	$1.85 \times 1.65 \times 0.300$				13.365 m ³
1940	$2.100 \times 1.600 \times 0.300$				19.152 m ³
140	$1.85 \times 1.50 \times 0.300$				0.8325 m ³
					$\Sigma 139.279 \text{ m}^3$

② Pl Maintenance of

Gravel Shoulder	5m				
324	8.600×1.100				302.720 m ²
324	2.85×1.100				319.495 m ²
134	3.500×1.100				50.050 m ²
304	3.030×1.100				99.990 m ²
14	1.400×1.100				1.540 m ²
					$\Sigma 773.795 \text{ m}^2$

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B.P.	21407870	
less 10 ft below					
as per Agreement			(-)	21408000	
				19267000	

vibash
29/06/2023
JO