

Particulars	Details of actual measurement				Contents of area	
	No.	L.	B.	D.		
<u>1st Year Maintenance</u>						
Name of work - L.O.S.G.						
to Gaidi Tola.						
Authority - E.E.R.D.						
Dalsinghsarai.						
Agg. - Chakradhar Choudhary.						
At + Po. - Kewara, P.S. -						
Dalsinghsarai, Dist -						
Samastipur.						
Agg. No - 53 SBD/2018-19						
Date of start - 24/01/2019.						
Date of comp. - 23/07/2020.						
A/D/C - 22/07/2020						
Work done -						
① Restoration of raincuts						
with soil -						
$90 \times 1.50 \times 1.70 \times 0.30 = 82.62 m^3$						
② Making up of earthen						
shoulder -						
$93 \times 4.95 \times 1.10 = 506.39 m^3$						
③ Maintenance of hume						
pipe culvert -						
$1 \times 3 nos = 3 Nos.$						

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
B.F. Amount					63808 = 00
		0.20 Km	(2)	At 8.29	
					= 130 = 00
(6) Cutting of branches of trees and shrubs					
Qty vide P.No. (23) of TMB.					
3 Nos			(2)	105.39	
					= 316 = 00
(7) Cutting of shrubs from roadway					
Qty vide P.No. (23) of TMB.					
13 Nos			(2)	6.47	
					= 84 = 00
(8) White washing of parapet walls					
Qty vide P.No. (23) of TMB					
61.92 m ²			(2)	16.54	
					= 1024 = 00
					= 65362 = 00
Less 10% Below			(2)	6536 = 00	
					= 58826 = 00
Grand					
20/7/2021					
J.E.					