

1st year maintenance

Area of work - Maintenance of Road

Bau Toy Bathus to Sihoma

Jala - minor Boulders Schur

Any - Touch security services

DRT 2021

Adm - 08 Sept 2021 - 22

Desert Gound — 10/3/2022

Desert Gound — 15/3/2023

① Restoration of Runn cuts

with all Creepches —

10 x 15m &  $90 \times 30 = 40.50 \text{ m}^3$

2x10m &  $.75 \times .30 = 4.50$

1x5m &  $.75 \times .30 = 1.125$

$46.125 \text{ m}^3$

Continuation line 45-282 m<sup>3</sup>

**Sch. XLV-Form No. 134**

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				B12/B	35,924 :-
Loss 0.04 ft below d floor B				(→ 14)	
Add 18 Y. GSF P 1st flwr				A	35210 :-
Add SRF				B	6690 :-
				B	196 :-
				B	42096 :-
				<del>AB</del> 15/3/2018 B	