


Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4th year maintenance					
Amount of work done					
at Road from T63 to Kharwan					
along under NDB Boring					
Aug - Chakardhar chandham					
Andon - 53 SBD / 20/8-19					
Date of Completion - 12.5.2020					
Decision - 6/5/2024					
① Restoration of					
bank cut & masonry					
$2 \times 10 \times 15m \times 90 \times 30 = 810m^3$					
$2 \times 10 \times 15m \times 75 \times 30 = 6750$					
					148.50m ³
				Limit	146.61m ³
2. masonry up & down					
2. Shoring with all complete					
$10 \times 2 \times 15m \times 90 = 270$					
$10 \times 2 \times 15m \times 75 = 225$					
$10 \times 2 \times 15m \times 60 = 180$					
$10 \times 2 \times 15m \times 60 = 180$					
$2 \times 1 \times 15 \times 45 = 1350$					
					868.50m ²
				Limit	865.41m ²
3. Repair & put holes					
filled with 25mm mm					
with all complete					

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				1314	243901-
6/10 cutting of branch & trees					
cutting under 159					
72 @ 316					
105-39/2h				316	
					244217-
104. bend					244227
					2197952
 6/8/2024					