

Sch.XLV-Form No. 134

--	--	--	--	--	--

Best year's maintenance				
-------------------------	--	--	--	--

Name of work: — Maintenance of

road from Gehuni to phulbigha

Agency: — Sri Sarvag Kumar —

Agreement No:	22830	19-20
---------------	-------	-------

Date of completion: - 28-8-20

Record entry

(1) Restoration of Rain cuts

2X 8 Nos	X 3M	X 1.0X	-30 =	14.40m
2X 4 Nos	X 4M	X 1.0X	-30 =	9.60m
2X 6 Nos	X 3.5M	X 1.0X	-30 =	11.34m
2X 10 Nos	X 2.75M	X 1.0X	-30 =	14.85m
2X 12 Nos	X 2.50M	X 1.0X	-30 =	14.40m
2X 5 Nos	X 1.00M	X 1.0X	-30 =	2.77m

Continuation

67.38m

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5) Patch repair over bitu- minious surface					
vide T.M.B. P (30) = 31.20 m ²					
				@ 307.82/20	Rs 6042
(6) Maintenance of H.P. channel					
vide T.M.B. P (30) = 6 Nos.					
				@ 1117.8/20	Rs 6702
(7) Maintenance of road sign					
vide T.M.B. P (30) = 1.33 km					
				@ 1074.51/km	Rs 1429
(8) Maintenance of K.M. 3200 M					
vide T.M.B. P (31) = 1.33 km					

(9) Trimming of grass					
vide T.M.B. P (31) = 2995 m ²					Rs 2420
				@ 2.18 /m ²	Rs 6527
					Rs 83064
Less 10% As Agreement					Rs 8306
					Rs 74758

Statement of Materials

Spot - 0.09 m ³					
(1) patch repair = 31.20 m ²					
(2) removal of loose material = 31.20 m ²					
Stone chip M = 1.68 km ³					

S/Material = 1.27 m³

Continuation

Mitumini's-90 + B.S.D + R.S.D ~~can~~ Balance
vide p. (27) of the H.B.

Rs 30000.00
30000.00

2nd year maintenance.

34.

Sch.XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work :- Maintenance of					
road from Gohini to full bridge					
Agency :- Sri Sanjay Kumar					
Agreement No :- 225130/19-20					
Date of completion :- 28.8.20.					
(1) Restoration of Painscuts					
2x10 Nos	4.0x	1.0x	30	= 24 m ³	
2x6 Nos	3.0x	1.0x	30	= 10.80 m ³	
2x12 Nos	3.5x	1.0x	30	= 25.20 m ³	
2x14 Nos	3x	2.5x	1.0x	= 21.00 m ³	
				81.0 m ³	
				Unit - 80.86 m ³	

(2) Maintenance of earthwork					
Shoulder					
	2x15 Nos	4.0x	1.0x	2.0	$= 120m^2$
	2x6 Nos	3.0x	1.0x	2.0	$= 36m^2$
	2x16 Nos	3.5x	1.0x	2.0	$= 112m^2$
	2x18 Nos	2.5x	1.0x	2.0	$= 90m^2$
	2x20 Nos	2.8x	1.0x	2.0	$= 91.20m^2$
					$449.20m^2$

(3) Repair of pot holes					
	10 Nos	0.61x	0.42x	0.075	$= 0.19m^3$

(4) Patch repair over bitumin surface					
	20 Nos	0.40x	0.30		$= 2.4m^2$
	30 Nos	0.90x	0.60		$= 16.20m^2$
	18 Nos	0.80x	0.55		$= 7.92m^2$
	22 Nos	0.50x	0.45		$= 4.95m^2$
	15 Nos	1.50x	1.20		$= 27.00m^2$

Continuation					
	16 Nos	0.56x	0.44		$= 3.94m^2$
					$62.41m^2$
					Unit 62.39 m ²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

	No.	L	B.	D.	Area
G) cutting of shrub from road way.					
wide T.M.B-P-(35)		13.31	Mos		
@ Rs 6.54/m ²				Rs 87.05=	
H) Trimming of grass					
wide T.M.B-P-(35)=		2925m ²			
@Rs 2-18/m ²				/Rs 5922=	
I) whitewashing of parapet-					
wide T.M.B-P-(35)=		126m ²			
@Rs 16-24/m ²				/Rs 2042=	
Total mt 4y AC			MT.	A 123 478 ru - 12848 = A 11130 = 30-04-22	

Material: Chabernant
 E/W = 80-86 m³
 S/chip = 4-36 m³
 S/metal = 0-28 m³
 Hh
 30 3.22
 24 m³
 A. G.

Scanned with CamScanner

Continuation

B.F.B 97355

Continuation