

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W:-	Maint ⁿ of road from				
	LOH to Sahaspur				
	Aarypur Bhumihar Tola				
	Dist.				
Agg:-	Chitrangan Kumar				
Agg NO:-	59 SBD/2018-19				
Actual Date of Comp:-	07.09.19				
	Measurement				
①	Reformation of rain cuts				
	with soil - do - do				
	comp. job -				

$$3 \times 10.0 \times 0.9 \times 0.3 = 8.10$$

$$4 \times 14.0 \times 0.8 \times 0.3 = 13.44$$

$$4 \times 5.00 \times 0.50 \times 0.3 = 3.00$$

$$4 \times 8.00 \times 0.80 \times 0.30 = 7.680$$

$$5 \times 9.00 \times 0.90 \times 0.30 = 12.150$$

$$= 44.370 \text{ M}^3$$

②	Maintenance of earthen				
	shoulder - do - do - compen.				
	12	5.0	1.05	=	63.00
	10	4.0	1.00	=	44.00
	8	5.0	1.125	=	45.00
	6	5.0	0.80	=	24.00
	8	6.0	1.05	=	50.40
	5	6.0	1.00	=	24.00
	Continuation				
					= 250.40 M ²

Scanned with CamScanner