

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य सिमरी बख्तियारपुर।

पत्रांक:- 1059/2024

सिमरी बख्तियारपुर दिनांक:- 28.05.2024

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सिमरी बख्तियारपुर।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
ब्राडा, पटना।

विषय:- 3054 बिहार ग्रामीण पथ नई अनुरक्षण नीति 2018 के योजना अन्तर्गत में
अधियाचित राशि का आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषयक प्रासंगिक पत्र के अनुपालन में 3054 बिहार ग्रामीण पथ नई
अनुरक्षण नीति 2018 के योजना अन्तर्गत राशि की माँग संलग्न विहित प्रपत्र में पथवार की
गई है।


अतः भवदीय से अनुरोध है कि विहित प्रपत्र के कॉलम 18 में अंकित कुल राशि
का आवंटन उपलब्ध कराने की कृपा की जाय। अधियाचित राशि के संदर्भ में Bump
Intrigater Report की छाया प्रति संलग्न कर समर्पित किया जा रहा है।

अनु० यथोक्त।

विश्वासभाजन


28/05/24

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सिमरी बख्तियारपुर।


28/05/24

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Division : Simri Bakhtiyarpur

Sl. No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allotted Amount (I Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (In lac)	Requisition Against work done (In lac)	Remarks
					Length (In Km)	Amount (in Lac)	Initial Rectification with Surface Renewal (in lac)	5 years Routine Maintenance (In lac)											
1	RM/SA/SIM/24/0002	The house fo Sri Madhav singh at Jamhara to lamahara village.	20904401021	Letter no-6120 Dated-04.12.2023	0.450	27.69000	23.38969	2.53000	28 MBD/2023-24/16.03.2024	15.12.2024	27.05.2024	2.510	Full PCC Work	Full PCC Work	0.00000	0.00000	23.38969	23.38969	Road Complete
2	RM/SA/SIM/24/0002	1.028 - Molodha mushari To Belhat (VR12)	20904402018	Letter no-6120 Dated-04.12.2023	2.534	147.19800	92.46248	24.71810	28 MBD/2023-24/16.03.2024	15/12/2024	27.05.2024	3.216	25mm	5.02%	0.00000	0.00000	92.46248	92.46248	Road Complete
3	RM/SA/SIM/24/0003	BISHANPUR PANCHAYAT MAIN ROAD TO KAMLESHWARI YADAV HOUSE	20904412036	Letter no-6120 Dated-04.12.2024	1.200	60.35600	38.47153	11.51000	28 MBD/2023-24/16.03.2024	15/12/2024	27.05.2024	2.663	25mm	5.02%	0.00000	0.00000	38.47153	38.47153	Road Complete

27/05/24

Executive Engineer
RWD Works Division
Simri Bakhtiyarpur
27/05/24

Form GFR 19- A
(See Government of India's Decision (I) below Rule - 150)
Form of Utilization Certificate upto the month of May -2024
New Maintenance Policy 2018

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lacs)	Amount Received (in lacs)	Particulars
1	1	Letter No 69 Dated 06.05.2024	Rs 5414.86403 Vide Letter No 69 Dated 06.05.2024	Certified that out of RS 5249.90542 lacs of grants in aid sanctioned during the Years up to 2024-25 in favour of Executive Engineer, RWD Works Division Simri Bakhtiyarpur under this Department, a sum of Rs 5198.39269 lacs has been utilized for the purpose of New_MR Scheme remaining 98.63304 unutilized at the end of the period under report.
		Total :	5414.86403	

Certified and verified myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of Checks exercised :-

- i Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii Construction material have been tested.
Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- iv All other codal formalities have been observed.

Physical Progress achieved :-

- i Construction of Road works.
- ii Construction of CD works

Sr D.A.O
RWD works Division
Simri Bakhtiyarpur

Executive Engineer
RWD works Division
Simri Bakhtiyarpur

2606
27/05/24
MA
27/05/24

Name of work	: L028 - Molodha mushari To Belhat (VR12)	
Name of customer	: Raja Traders (Prop- Bipin Kumar Jha)	
(R)Rural Road		
Good	Average	Poor
< 4000	4001 - 5000	> 5000

Date	Time	Test No	Distance(m)	Total Distance(m)	BUMP(cm)	Speed(Km/Hr)	UI(mm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
21/5/2024	14:23:01	43	0	0	0.0 cm	15.7 Km/Hr	0.0 mm/Km	88	0.17	Good	25.702945	N	86.824701	E	Normal
21/5/2024	14:23:17	43	100	100	29.0 cm	15.6 Km/Hr	2900.0 mm/Km	2797	3.78	Good	25.702945	N	86.824701	E	Normal
21/5/2024	14:23:34	43	100	200	24.0 cm	25.9 Km/Hr	2400.0 mm/Km	2330	3.21	Good	25.702945	N	86.824701	E	Normal
21/5/2024	14:23:53	43	100	300	22.0 cm	24.6 Km/Hr	2200.0 mm/Km	2143	2.98	Good	25.702945	N	86.824701	E	Normal
21/5/2024	14:24:12	43	100	400	29.0 cm	20.0 Km/Hr	2900.0 mm/Km	2797	3.78	Good	25.705405	N	86.829145	E	Normal
21/5/2024	14:24:30	43	100	500	24.0 cm	25.9 Km/Hr	2400.0 mm/Km	2330	3.21	Good	25.705405	N	86.829145	E	Normal
21/5/2024	14:24:47	43	100	600	22.0 cm	24.6 Km/Hr	2200.0 mm/Km	2143	2.98	Good	25.705405	N	86.829145	E	Normal
21/5/2024	14:25:03	43	100	700	25.0 cm	27.0 Km/Hr	2500.0 mm/Km	2423	3.33	Good	25.705405	N	86.829145	E	Normal
21/5/2024	14:25:33	43	100	800	29.0 cm	15.6 Km/Hr	2900.0 mm/Km	2797	3.78	Good	25.704697	N	86.836225	E	Normal
21/5/2024	14:25:49	43	100	900	24.0 cm	26.2 Km/Hr	2400.0 mm/Km	2330	3.21	Good	25.704697	N	86.836225	E	Normal
21/5/2024	14:26:22	43	100	1000	23.0 cm	28.5 Km/Hr	2300.0 mm/Km	2237	3.1	Good	25.704697	N	86.836225	E	Normal
21/5/2024	14:26:43	43	100	1100	29.0 cm	15.6 Km/Hr	2900.0 mm/Km	2797	3.78	Good	25.704697	N	86.836225	E	Normal
21/5/2024	14:26:56	43	100	1200	22.0 cm	24.6 Km/Hr	2200.0 mm/Km	2143	2.98	Good	25.704697	N	86.836225	E	Normal
21/5/2024	14:26:56	43	100	1300	24.0 cm	25.9 Km/Hr	2400.0 mm/Km	2330	3.21	Good	25.702627	N	86.829608	E	Normal
21/5/2024	14:26:57	43	100	1400	27.0 cm	17.4 Km/Hr	2700.0 mm/Km	2610	3.56	Good	25.702627	N	86.829608	E	Normal
21/5/2024	14:26:57	43	100	1500	29.0 cm	15.6 Km/Hr	2900.0 mm/Km	2797	3.78	Good	25.702627	N	86.829608	E	Normal
21/5/2024	14:26:42	43	100	1600	22.0 cm	24.6 Km/Hr	2200.0 mm/Km	2143	2.98	Good	25.702627	N	86.829608	E	Normal
21/5/2024	14:31:05	43	100	1700	24.0 cm	25.9 Km/Hr	2400.0 mm/Km	2330	3.21	Good	25.702627	N	86.829608	E	Normal
21/5/2024	14:31:16	43	100	1800	22.0 cm	24.6 Km/Hr	2200.0 mm/Km	2143	2.98	Good	25.702627	N	86.829608	E	Normal
21/5/2024	14:31:35	43	100	1900	24.0 cm	25.9 Km/Hr	2400.0 mm/Km	2330	3.21	Good	25.702627	N	86.829608	E	Normal
21/5/2024	14:31:55	43	100	2000	22.0 cm	24.6 Km/Hr	2200.0 mm/Km	2143	2.98	Good	25.700772	N	86.832427	E	Normal

21/05/24
86

21/05/2024
MST




Name of work :	L028 - Molodha mushari To Belhat (VR12)		
Name of customer :	Raja Traders (Prop- Bipin Kumar Jha)		
(R)Rural Road			
Good	Average	Poor	
< 4000	4001 - 5000	> 5000	

27/5/2024	14.32.17	43	100	2100	24.0 cm	25.9 Km/Hr	2400.0 mm/Km	2330	3.21	Good	25.700772	N	88.832427	E	Normal
27/5/2024	14.32.35	43	100	2200	29.0 cm	15.6 Km/Hr	2900.0 mm/Km	2797	3.78	Good	25.700772	N	88.832427	E	Normal
27/5/2024	14.32.57	43	100	2300	24.0 cm	25.9 Km/Hr	2400.0 mm/Km	2330	3.21	Good	25.700772	N	88.832427	E	Normal
27/5/2024	14.33.07	43	100	2400	26.0 cm	23.8 Km/Hr	2600.0 mm/Km	2517	3.44	Good	25.700772	N	88.832427	E	Normal
27/5/2024	14.33.07	43	100	2500	24.0 cm	25.9 Km/Hr	2400.0 mm/Km	2330	3.21	Good	25.700772	N	88.832427	E	Normal
27/5/2024	14.33.07	43	100	2600	29.0 cm	15.6 Km/Hr	2900.0 mm/Km	2797	3.78	Good	25.700772	N	88.832427	E	Normal

ma
27.05.2024
A1TM

27/05/24
86





mm
7.05.2024
AITM

SM
27.05.24
Bk

Name of work : BISHANPUR PANCHAYAT MAIN ROAD TO KAMLESHWARI
YADAV HOUSE

Name of customer : Raja Traders (Prop- Bipin Kumar Jha)

(R) Rural Road

Good

Average

Poor

< 4000

4001 - 5000

> 5000


Date	Time	Test No	Distance(m)	Total Distance(m)	BUMP(cm)	Speed(Km/Hr)	UI(mm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
27/05/2023	11:16:35	41	0	0	0.0 cm	15.7 Km/Hr	0.0 mm/Km	88	0.17	Good	25.852423	N	86.775045	E	Normal
27/05/2023	11:18:05	41	100	100	22.0 cm	13.9 Km/Hr	2200.0 mm/Km	2143	2.98	Good	25.852423	N	86.775045	E	Normal
27/05/2023	11:18:05	41	100	200	25.0 cm	44.5 Km/Hr	2500.0 mm/Km	2423	3.33	Good	25.852423	N	86.775045	E	Normal
27/05/2023	11:18:05	41	100	300	24.0 cm	37.8 Km/Hr	2400.0 mm/Km	2330	3.21	Good	25.852423	N	86.775045	E	Normal
27/05/2023	11:18:05	41	100	400	12.0 cm	25.9 Km/Hr	1200.0 mm/Km	1209	1.79	Good	25.852096	N	86.774519	E	Normal
27/05/2023	11:20:40	41	100	500	25.0 cm	44.5 Km/Hr	2500.0 mm/Km	2423	3.33	Good	25.852096	N	86.774519	E	Normal
27/05/2023	11:20:40	41	100	600	24.0 cm	37.8 Km/Hr	2400.0 mm/Km	2330	3.21	Good	25.852096	N	86.774519	E	Normal
27/05/2023	11:22:06	41	100	700	17.0 cm	16.8 Km/Hr	1700.0 mm/Km	1676	2.4	Good	25.850631	N	86.771016	E	Normal
27/05/2023	11:22:06	41	100	800	22.0 cm	13.9 Km/Hr	2200.0 mm/Km	2143	2.98	Good	25.850631	N	86.771016	E	Normal
27/05/2023	11:26:28	41	100	900	25.0 cm	44.5 Km/Hr	2500.0 mm/Km	2423	3.33	Good	25.850631	N	86.771016	E	Normal
27/05/2023	11:26:28	41	100	1000	16.0 cm	27.0 Km/Hr	1600.0 mm/Km	1583	2.28	Good	25.852924	N	86.76593	E	Normal
27/05/2023	11:26:28	41	100	1100	24.0 cm	37.8 Km/Hr	2400.0 mm/Km	2330	3.21	Good	25.852924	N	86.76593	E	Normal
27/05/2023	11:28:22	41	100	1200	17.0 cm	16.8 Km/Hr	1700.0 mm/Km	1676	2.4	Good	25.852924	N	86.76593	E	Normal

Maulin
27.05.2024
AITM

Abhi
27/05/24
JB

27/05/24
BB





Maul
27.05.2024
ALTM

864
27/05/24
86

Name of work : The house fo Sri Madhav singh at jamhara to lamahara village.

Name of customer : Raja Traders (Prop- Bipin Kumar Jha)

(R)Rural Road

Good

Average

Poor

< 4000

4001 - 5000

> 5000


Date	Time	Test No	Distance(m)	Total Distance(m)	BUMP(cm)	Speed(Km/Hr)	UI(mm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
27/5/2024	12:16:35	42	0	0	0.0 cm	15.7 Km/Hr	0.0 mm/Km	88	0.17	Good	25.779328	N	86.78672	E	Normal
27/5/2024	12:16:35	42	100	100	16.0 cm	7.1 Km/Hr	1600.0 mm/Km	1583	2.28	Good	25.779328	N	86.78672	E	Normal
27/5/2024	12:16:35	42	100	200	28.0 cm	43.6 Km/Hr	2800.0 mm/Km	2704	3.67	Good	25.779328	N	86.78672	E	Normal
27/5/2024	12:18:19	42	100	300	25.0 cm	44.5 Km/Hr	2500.0 mm/Km	2423	3.33	Good	25.77598	N	86.787958	E	Normal
27/5/2024	12:18:19	42	100	400	16.0 cm	27.0 Km/Hr	1600.0 mm/Km	1583	2.28	Good	25.77598	N	86.787958	E	Normal
27/5/2024	12:18:19	42	100	500	25.0 cm	44.5 Km/Hr	2500.0 mm/Km	2423	3.33	Good	25.77598	N	86.787958	E	Normal

Maun
27.05.2024
A I T M

8/6
27/05/24
BB



Name of Customer: Raja Traders (Prop- Bipin Kumar Jha) , Machine no: 19215 , Road: The house fo Sri Madhav singh at Jamhara to lamahara village. , Date: 28/05/24 , Section No: 41 , Equation: $Y=0.934X+88.4$



Maul
27/05/24
A2TM

Su
27/05/24
80