

511011

माधुसूदन :-

Schedule XLV From No. 134.

11/10/57 (Mali Chowk) Bishanpur To Kanjarpur
DIVISION

SUB-DIVISION

W. B. No-190 / 17-18

Measurement Book

Tai Water Division

10

પ્રમાણિત વિધા જારા છે કિંમત
માપી હાત મે મશીન દ્વારા અંકિત
કુલ 100 (૧૦૦ સીપ-નેટ) જે
અવધિમાં લેવામાં આવેલા અર્થમાં
વેલ દોરે છે વિગત વિધા જારા છે

[Signature]
29.04.17

કાર્યવાહક અધિકારી
પ્રામીય કાર્ય વિભાગ
કાર્ય પ્રવંડલ-ગોવરી

Sony 91
29.4.17

Sch. XLV-Form No. 134

DIVISION

SUB-DIVISION

Measurement Book

No. 190/
17-18

Name of officer _____

Date of first entry _____

Date of last entry _____

Est of Bill.

M.B.No-130/17-18

1

Name of work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W → Cons of Road					
from NH-107 (Mali					
chowk) To Kanjari)					
Road under Mabard)					
during. 2017-18					
Agency → M/s Jai Mata Di Construction					
Aq. Value Rs — 3,91,24,678/-					
Dt of Commenc. - 29.4.17					

Dt of Comp. - 28-4-18

(1) Cleaning and Grubbing of road.

$$5027 \times 6.50 = 32675.50$$

$$8 \quad 32675.50 / 10000 = 3.27 \text{ Hae.}$$

(2) Cons of embankment -

Mater obtained

from borrow pits

do — do

As - - do

~~Page~~

~~12/05/2020~~
J2

~~12/05/2020~~
20/12/20

2nd year Maintenance

ABSTRACT OF WST.

① Restoration of sari
cubs / Berms with soil
do — do — do

vide of P. No (42) of this MB

phy - 811.529 m³

@ 324 = 98/m³ - 263731

Continuation

to 263731 = m

② Making of Berms /
Shoulder, stripping
excess soil from the
Shoulder — do — do —

vide P.No (44) of this MB
Qty — 2258.425 m²

@ Rs 48 = 39/m² — Rs 109888

③ Patch repairs over
Bituminous surface

with Seal Coat —
do — do — do

vide P.No (45) of this MB
Qty — 131.365 m²

@ Rs 271 = 56/m² — Rs 35673

④ Maintenance of CD
work — do — do —

vide P.No — (45) of this MB
Qty — 939 m

@ Rs 939 = 293/m — Rs 940 =

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑤ Maintenance of road dign - do - do - do					
vide P. No. ④⑤ of this m/s					
Qty - 5.03 km					
Qty 923 = 36/k - 4644 =					
⑥ Maintenance of work of km stone - do -					
do - do - do					
vide P. No. ④⑤ of this m/s					

Qty - 5.03 km					
Qty 459 = 74/k - 2312 =					

⑦ White washing of Parapet wall of CD					
do - do - do					
vide P. No. ④⑥ of this m/s					
Qty - 18.96 m ²					
Qty 322 = 34/m ² - 613 =					
Qty 17201					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		BF	—	4.47201 m	
Coas 10% Bchms				4.47202	
				4.375481 m	

[Signature]
20/05/2020
JE

OP
Attended
28/2/2022
JE

[Signature]
20/5/2020
AB

Material Statement

① Gravel — 1650-300 m³

② Stone chips — 3.55 m³

③ Coarse sand — 0.79 m³

④ Bitumen emulsion — 39.41 kg

⑤ Bitumen-5-90 — 281.13 kg

[Signature]
20/05/2020
JE

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd year Maintenance					
ABSTRACT OF WT					
① Restoration of rain cuts/Berms with soil					
do — do — E_2					
946.83m ² — TMBP — (52)					
@ 324298/m ² — 3077092					
② Making of Berms/ Shoulder, dropping excess soil from the shoulder — do — do — E_2					
2614.65m ² — TMBP — (54)					
@ 48259/m ² — 127045					
③ Patch repairs over Pit holes Bituminous surface with 20mm Acrylic Carpet with Seal Coat — do — E_2					
257.69m ² — TMBP — (54)					
@ 271256/m ² — 6997820					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
④ Patch repair over bituminous surface with 20mm Premix carpet with 600g bent — do — do — 25 :					
262.16 m ² — T.M.B.P. — (55)					
@ 2712 56/m ² — 171192 =					
⑤ Maintenance of W.B.M road — do — do —					
19.327 m ² — T.M.B.P. — (56)					
@ 4462 80/m ³ — 8635 =					
⑥ Maintenance of G. work — do — do —					
of M.S. — T.M.B.P. — (56)					
@ 919293/m ² — 920 =					
4 585471 =					
Less 10 % Bols w — 585472					
Rs 269242					

Continuation
10/06/2022
Jr.
A.K. Humal
23/7/2022
16/6/2024
AE

5th year maintenance

72

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: Construction of Road from N.H. 107C Malichauk to Kanjari					
Name of Agency - M/S Jai mala di Construction					
Agreement No.					
Date of start				29-4-2017	
Date of comp				28-04-2018	
Agreement value					

① Restoration of Rainwater
Berm with Soil moun
etc - da —

2 x 5 x 3000 x 1.00 x 0.30 = 90.00	
2 x 2 x 30.00 x 1.00 x 0.30 = 36.00	
2 x 3 x 30.00 x 1.00 x 0.30 = 54.00	
2 x 5 x 3000 x 1.00 x 0.30 = 90.00	
2 x 6 x 3000 x 1.00 x 0.30 = 108.00	
2 x 5 x 3000 x 1.00 x 0.30 = 90.00	
2 x 6 x 3000 x 1.00 x 0.30 = 108.00	
2 x 5 x 3000 x 1.00 x 0.30 = 90.00	
2 x 6 x 3000 x 1.00 x 0.30 = 108.00	
2 x 5 x 3000 x 1.00 x 0.30 = 90.00	
2 x 6 x 3000 x 1.00 x 0.30 = 108.00	

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of berms with soil morum - do - Qty. vid T.M. B.P. H. (72) ilum (1) 1221.56 ② 324.98 m ² = 396982					
② maky up of berms Shoulder stripping Excess soil Qty. vid T.M. B.P. H. (73) ilum (2) 3390.00 ③ 48.59 m ² = 164720					
③ maintenance of w.B.M. Surface on road - Qty. vid T.M. B.P. H. (74) ilum (3) 34.31 ④ 446.80 m ² = 15330					
④ maintenance of patches over pits holes with 20.0 mmp mix Qty. vid T.M. B.P. H. (75) ilum (4) 461.40 ⑤ 271.56 m ² = 125298					
Continuation Total - 702330					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5) Potahraiv over path menul Seabone width 80.00 m Qty vial T.M.B.P.H. 96 ilw 155 Qty 462.49 Ans. $271.56 / m^2 = 125593 =$					
(6) maintenance of c.d works Qty vial T.M.B.P.H. ilw 11 514.00 1140 Ans. $939.93 / 1140 = 939 =$					
(7) cutting of branch of Tree Qty vial T.M.B.P.H. ilw 11 Qty 844 Ans. $88.41 / 11 = 767.00$					
(8) cutting of shrubs from road side Qty vial T.M.B.P.H. ilw 11 Qty 3611 Ans. $5.21 / 11 = 187.00$					
Continuation Total - 829756 =					

Continuation