

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Sth on file Bill					
Sth year maintenance Bill					

Name of Work - maintenance of road from Bhalpatti to Mahesh Patti under Darbhanga Block.

Agency - Madan Thakur.

Ag. No - 67 SBA/2018-19 (mmgsy-sc)

Actual Date of completion - 17.09.2019.

Date of measurement :-

Measurement

- ① Restoration of rain cuts/Berms with Soil, macrum etc
- - - all complete.

1x15.00x0.75x0.30	= 3.38 m ³
1x20.00x0.60x0.30	= 3.60 m ³
1x25.00x0.70x0.30	= 5.25 m ³
3x13.50x0.60x0.25	= 6.07 m ³
5x12.30x0.65x0.30	= 11.99 m ³
2x24.00x0.75x0.275	= 9.90 m ³
3x15.00x0.60x0.30	= 8.10 m ³
3x12.00x0.75x0.30	= 8.10 m ³
2x11.00x0.65x0.25	= 3.58 m ³
2x10.00x0.65x0.30	= 3.90 m ³
	63.87 m ³

- ② making up of Berms/shoulder stripping excess Soil etc
- - - all complete.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4x	22.00	x 0.70	=	61.60 m ²	
3x	18.00	x 0.70	=	37.80 m ²	
1x	28.00	x 0.60	=	16.80 m ²	
2x	24.50	x 0.65	=	31.85 m ²	
2x	30.00	x 0.60	=	36.00 m ²	
3x	19.00	x 0.70	=	39.90 m ²	
1x	25.00	x 0.65	=	16.25 m ²	
5x	15.00	x 0.60	=	45.00 m ²	
4x	12.50	x 0.70	=	35.00 m ²	
3x	24.00	x 0.60	=	43.20 m ²	
				363.40 m ²	

③ Repair of Pot holes With 75mm Bm to 11.2mm M.S.S. - all complete.

1x	7.25	x 1.50	x 0.075	=	0.81 m ³
1x	6.75	x 1.60	x 0.075	=	0.81 m ³
1x	5.40	x 1.20	x 0.075	=	0.49 m ³
1x	6.00	x 1.55	x 0.075	=	0.70 m ³
				2.81 m ³	

④ Patch repair over Pot holes

With 11.2mm to 0.9mm M.S.S.

--- all complete.

1x	7.25	x 1.50	=	10.88 m ²
1x	6.75	x 1.60	=	10.80 m ²
1x	5.40	x 1.20	=	6.48 m ²
1x	6.00	x 1.55	=	9.30 m ²
			37.46 m ²	

⑤ maintenance of C/P works

(C.P. culvert) --- all complete.

4, 2 Nos.

Continuation

Continuation

Sch. XLV-Form No. 134					
Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of cost</u>					
1/66. Restoration of Raincuts/Berms					
With Soil, macrum etc - - -					
all complete.					
Qty V.T.M.B.P-68 = 63.87 m ³					
@Rs 390.29/m ³ ----- Rs 24928=00					
2/67. making up of Berms/Shoulder,					
stripping excess soil - - -					
all complete.					
Qty V.T.M.B.P-69 = 363.40 m ²					
@Rs 52.17/m ² ----- Rs 18959=00					
3/68. Repair of Pot holes filled					
With 75 mm. Bm. - - -					
all complete.					
Qty V.T.M.B.P-69 = 2.81 m ³					
@Rs 10198.67/m ³ ----- Rs 28658=00					
4/69. Patch repair over Pot holes					
With 11.20 mm to 0.90 mm.					
m.s.s. - - - all complete.					
Qty V.T.M.B.P-69 = 37.46 m ²					
@Rs 213.38/m ² ----- Rs 7993=00					
5/70. maintenance of C/D Work					
(U.P. culvert) - - - all complete.					
Qty V.T.M.B.P-69 = 2 Nos.					
@Rs 1131.64 each ----- Rs 2263=00					
6/71. Cutting of branches of tree					
and shrubs - - - all complete.					
Qty V.T.M.B.P-70 = 1 Nos					
@Rs 118.23 each ----- Rs 118=00					
Continuation Rs 118=00					
Rs 82919=00					
C.O.					

