

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

4th year Maintenance

N/A agency - ~~Contract~~ Maintenance

of road from S.O. to

Bakipur under M.H. 47

N/A agency - Smt. Titendrasing

Kumar.

Agg. No - B/M/434/SB/D/

2019-20.

D/Start - 29/08/2019

D/Complete - 28/08/2020

Actual at of CompL - 28/08/2020

D/CompL - 10/08/2024

1.) Rectification of remains

from - do - do - all

Completed

 $2 \times 6.30m \times 0.90m \times 0.30 = 3.40m^3$ $1 \times 9.30m \times 1.10m \times 0.20 = 3.02m^3$ $3 \times 21.0m \times 0.95m \times 0.30 = 17.95m^3$ $1 \times 16.30m \times 1.10m \times 0.30 = 5.379m^3$ $2 \times 11.0m \times 0.90m \times 0.30 = 5.94m^3$ $4 \times 17.50m \times 0.80m \times 0.20 = 16.80m^3$ $1 \times 27.30m \times 0.30m \times 0.30 = 2.45m^3$ $2 \times 21.30m \times 1.10m \times 0.30 = 12.28m^3$ $3 \times 14.15m \times 1.10m \times 0.30 = 14.0m^3$ $Q_h = 81.77m^3$ Limit - $81.36m^3$

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF GWT</u>					
1/151) Restoration of railway/					
form - do - do - do					
Complete to					
Qh - 81.36 m^2 vide TMS P-61					
@ R - $380.54/\text{m}^2$ A - 30959 = w					
2/152) Maintenance of culvert					
Shoulder - do - do - do					
Complete to					
Qh - 48.02 m^2 vide TMS P-62					
@ R - $5730/\text{m}^2$ A - 25861 = w					
3/155) Maintenance of W.D.B					
road - do - do - do					
Complete to					
Qh - 69.41 m^2 vide TMS P-63					
@ R - $356.88/\text{m}^2$ A - 24771 = w					
4/153) Repair to P.T. holes					
- do - do - do - do					
Complete to					
Qh - 69.41 m^2 vide TMS P-63					
@ R - $341.78/\text{m}^2$ A - 23695 = w					
5/157) Maint. of Gume pipe					
Culvert - do - do - do					
Complete to					
Qh - 0 y vide TMS P-63					
@ 1117.0/m A - 4468 = w					
Continuation A - 109754 = w					

Continuation of 114617-

Continuation