

1st year maintenance

41

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Repair of roof from 1st to 7th floor					
Agency - Radha Mohan Singh					
Agreement no - 29380/20.21					
Date of start - 11.12.2020					
Actual completion - 25.12.2022					
Report Entry					
(1) Measurement of work					
2x	3.25	1.10	0.30		2.48
3x	4.40	0.85	0.30		3.32
4x	6.60	0.60	0.30		4.25
6x	5.90	0.95	0.30		10.09
9x	6.25	0.80	0.30		4.86
2x	4.20	1.10	0.30		2.72
1x	4.90	1.05	0.30		1.54
3x	4.10	1.00	0.30		3.60
4x	7.90	0.95	0.30		9.01
5x	3.25	0.25	0.30		4.22
7x	4.40	0.70	0.30		6.42
9x	6.60	1.10	0.30		6.53
6x	6.90	0.90	0.30		10.32
Total					70.06

Continuation

material used	
Earth work -	70.06 m ²
Bitumen 5-90 -	70 lcs
S. Chips -	0.90 m² 0.90 m ²
Emulsion R-1	7 lcs
Crushed sand -	0.20 m ²

MB
 19/4/24
 JE

Scanned with CamScanner