

3rd Year Maintenance Bill

32

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work-	Maintenance of Road from				
Matalpur-	Tetrawan Daryapur Path To				
	Abishunbur Kolbiya.				
Agency-	Kumar Kartik.				
Agreement No-	SBD-601/2018-19				
Date of Commencement-	31/05/2019				
Date of completion-	29/07/20				
Actual date of completion-	14/02/20				
	Items				
① Restoration of roadcuts					
	8x	2.90x	1.20x	0.30	8.352 m ³
	4x	3.75x	1.20x	0.30	5.400 m ³
	8x	4.60x	1.20x	0.30	13.248 m ³
	6x	5.90x	1.20x	0.30	12.744 m ³
	2x	6.70x	1.20x	0.30	4.842 m ³
	2x	7.90x	1.20x	0.30	5.688 m ³
	2x	8.25x	1.00x	0.30	4.950 m ³
					55.224 m ³
② Maintenance of gutter shoulder					
	8x	4.75x	1.20		45.60 m ²
	12x	6.25x	1.20		90.00 m ²
	8x	7.25x	1.20		74.88 m ²
	4x	7.90x	1.20		37.92 m ²
	2x	10.40x	1.20		24.96 m ²
	4x	8.55x	1.20		41.04 m ²
					313.92 m ²

Continuation



ABSTRACT OF COST

34

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of main culverts					
.....	20				
503244 ² VTHB P-32					
@ Rs 36223/4 ²					Rs 20004.00
② Maintenance of gutter shoulder					
.....	20				
313.924 ² VTHB P-32					
@ Rs 53.70/4 ²					Rs 16858.00
③ Repair to pot holes					
.....	20				
2.0054 ³ VTHB P-33					
@ Rs 937614/4 ³					Rs 18799.00
④ Patch repair over surface					
.....	20				
27.774 ² VTHB P-33					
@ Rs 19677/4 ²					Rs 5464.00
⑤ Maintenance of H.A. Culvert					
.....	20				
2.0040 VTHB P-33					
@ Rs 112229/40					Rs 2245.00
⑥ Cutting of branches of Trees					
.....	20				
1.0040 VTHB P-33					
@ Rs 10658/40					Rs 107.00
⑦ Work on foot walls					
.....	20				
.....					Rs 63477.00

Continuation

Continuation

Sch. XLV-Form No. 194

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1st year maintenance bill					
Name of work - Maintenance of road					
from Malabarpet to					
Varigalpur path to Rushankur					
Kadaya					
Agency - Kumar Kartik					
Agreement No - S.B.D - 60/2018-19					
Date of commencement -					31/05/2019
Date of completion -					29/02/2020
Actual date of completion					14/02/2020
① Restoring of surface					
creta soil & MODUM					
etc. is complete					
8x 5.0m x 1.10 x 0.30 = 13.20m ³					
10x 6.0 x 1.0 x 0.30 = 18.0m ³					
9x 5.0 x 1.10 x 0.30 = 14.85m ³					
9x 6.0 x 0.95 x 0.30 = 15.39m ³					
					total. 61.44m ³
② Hacking of shoulder stripping					
excess soil in cem					
complete					
8x 5.0 x 1.10 = 44.0m ³					
10x 8.0 x 1.0 = 80.0m ³					
6x 5.0 x 1.10 = 33.0m ³					
10x 7.0 x 0.95 = 66.50m ³					
12x 8.0 x 0.90 = 86.40m ³					
8x 6.0 x 0.95 = 45.60m ³					
					total. 355.50m ³

Continuation

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				12.14	93323.24
(6) Maintenance of road					
Width 7.13 m					
Length 0.80 km			1028 = 63/4 m		862.24
(7) Maintenance of 240 m x 4 m					
Stone in cut					
Width 7.13 m					
Length 0.80 km			596 = 09/4 m		477.24
(8) Cutting of Branch of tree					
Width 7.13 m					
Length 0.110 km			106239 m		107.24
(9) White washing of wall					
Width 7.13 m					
Length 4.10 km					
			2418 = 361 m		671.24
				79440.24	
				7944.24	
			Less 10% AS per Agreement		
				71496.24	
				2012/24	
				AFS 78	

Continuation