

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>3rd year maintenance Bill</u>					
<u>Name of Work - Pmnsy Hansi</u>					
<u>malahi Hok hae Bhagavathu</u>					
<u>Ki road near to Hansi</u>					
<u>Kerel tak</u>					
<u>Name of contractor - m/s meruti</u>					
<u>enterprises</u>					
<u>Ag. No - 43/SBD/2019-20</u>					
<u>Rate - 10% Below</u>					
<u>ADOC - 12.03.2021</u>					
<u>Work Done</u>					

Item (1) Restoration of Rain
cuts/Berms -

2x	23.0	x	0.800	x	0.300	=	11.04 m ³
4x	15x	1.00	x	0.300	=	18.0	
6x	10x	0.700	x	0.300	=	12.60	
1x	20.0	x	1.00	x	0.300	=	6.0
2x	4x	30.0x	1.00	x	0.300	=	72.0
1x	3x	10.0	x	0.30	=	9.0	
							128.64 m ³

Item (2) Making up of Berry
Shoulder -

2x	30x	1.00	=	60.0m ²	
2x	27.50x	0.600	=	33.0m ²	
2x	2x	30x	0.600	=	72.0m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
80.0m ² vide TM Pg. 74					
@ Rs. 953.80/m ²					Rs. 76304 = ∞
					Rs. 5,50,686 = ∞
Less 10% Below ∞					Rs. 55,069 = ∞
Per agreement					Rs. 4,95,617 = ∞
					Seq. Rs. 4,95,617 = ∞
Sabit					
22/06/24					
JE					