

~~MSA~~

MMSY: Ziegler-Piller's
यव निर्माणा के पत्रिका का नाम है।

Schedule XLV-Form No.-134

$$\frac{51216H}{7965} = \frac{5675}{9}$$

DIVISION

कार्यपालक अध्यायन्ता

SUB-DIVISION

ग्रामीण कार्य विभाग;

कार्य प्रगुडल अरकट्टियल

MEASUREMENT BOOK

Mr. B. No 1184 / ~~2018-19~~
2019-20

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>2nd year maintenance Bill</u>					
<u>Name of Work - Tola</u>					
<u>Chapandiya to</u>					
<u>Paschim Tola (mmsv)</u>					
<u>Name of Agency - Sislay</u>					
<u>Construction, Vill</u>					
<u>Basemtpur West</u>					
<u>Champeran</u>					
<u>Aggrement No - 45/2019-202</u>					
<u>Date of work order - 28-1-2020</u>					
<u>Date of completion - 27-1-2021</u>					
<u>Actual date of comp - 31-3-2022</u>					

Date of measurement - 6-4-2024
Date of Entry - 6-4-2024

Record Entry

(1) Restoration of masonry

Cut with Soil

4 x 7.5m x 1.1m x 0.30m 9.9m³

6 x 4.5m x 1m x 0.30m 8.1m³

5 x 6m x 1.1m x 0.30m 9.9m³

7 x 3.5m x 1m x 0.30m 7.35m³

5 x 8m x 1m x 0.30m 12m³

3 x 1.5m x 1m x 0.30m 13.5m³

60.75m³

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(2) Maintenance of earthen shoulder					
5 x 16m x 0.9m					72m ²
4 x 18m x 0.8m					57.6m ²
3 x 20m x 0.9m					54m ²
2 x 2m x 0.9m					5.4m ²
					189m ²
(3) Repair to potholes by removal Bituminous Surface road					
3 x 2.5m x 0.7m					5.25m ²
2 x 2m x 0.8m					3.2m ²
3 x 1.5m x 0.6m					2.7m ²
4 x 3m x 0.8m					9.6m ²
					20.75m ²
(4) Maintenance of Slab culvert by way of clearing					
					3 Nos
(5) Maintenance of road Signal by					
					1.68 hrs
(6) painting road letter and signs on any place					
					132 Nos

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
(7) Maintenance at 200 metre km Station					0.150k 0.180k
(8) Cutting of branches at trees and shrubs from the road way					6 NOS
(9) Cutting of shrub from the road way					12 NOS
(10) Trimming of grass and weeds from the shoulder					
	2x10	30m	x	0.3m	480m ²
	2x15	m	x	0.35m	25.5m ²
					505.5m ²
(11) White washing two coats on parapet walls					
	2x4m	x	1m		8m ²
	2x4m	x	0.6m		4.8m ²
	2x4m	x	0.4m		3.2m ²
	4x	0.4m	x	0.6m	0.96m ²
					16.96m ²
Grand 614/1024 JE					6104m ² NE

Particulars	Details of actual measurements				Contents of area
	No.	L	B	D	
2nd year maintenance ABSTRACT OF COST					
(1) Restoration of main cuts with soil					
Qty vide TMBP 43 item 1					
60.75m ³ @ Rs 380.58/m ³					23120 =
(2) Maintenance of concrete shoulder					
Qty vide TMBP 44 item 2					
189m ² @ Rs 58.60/m ²					11075 =
(3) Repair pot holes by removal of Bituminous surface					
Qty vide TMBP 44 item 3					
20.75m ² @ Rs 339.24/m ²					7039 =
(4) Maintenance of slab culverts					
Qty vide TMBP 44 item 4					
3 nos @ Rs 2309.03/No					6927 =
(5) Maintenance of road sign by way					
Qty vide TMBP 44 item 5					
1.62km @ Rs 1074.51/km					1805 =
(6) Printing new letter and signs					
Qty vide TMBP 44 item 6					
					Rs-49966 =

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D.	
				B/C	49366 =
132 NOS @ RS 20.53 / NOS					70 =
(7) Maintenance of					
200 meter km					
Stone by way					
Qty vide TMBP 45 it 7					
150 km @ RS 29.07 / km					109 =
(8) Cutting of branches					
of trees and shrubs					
from the roadway					
Qty vide TMBP 45 it 8					
6 NOS @ RS 106.52 / NOS					639 =
(9) Cutting of Shrubs					
from the roadway					
Qty vide TMBP 45 it 9					
12 NOS @ RS 6.54 / NOS					78 =
(10) Trimming of					
grass and weed					
from the shoulder					
Qty vide TMBP 45 it 10					
505.5 m ² @ RS 2.18 / m ²					1102 =
(iv) White Washing two					
coats on parapet wall					
Qty vide TMBP 45 it 11					
16.96 m ² @ RS 16.65 / m ²					282 =
				Total RS	52246 =
Less 0.10% Below as per approved					52 =
Grand				RS	52194 =
8/4/24					
JE					