

कार्यालय
कार्यपालक अभियंता, ग्रामीण कार्य विभाग
कार्य प्रमंडल, दलसिंहसराय, समस्तीपुर

पत्रांक1454.....दलसिंहसराय / दिनांक14/11/24.....

प्रेषक, कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, दलसिंहसराय

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी,
सचिव -सह- प्राधिकृत पदाधिकारी, विहार
ग्रामीण पथ विकास एजेंसी पटना।

विषय- **New Maintenance Policy 2018** योजनान्तर्गत पथ में आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में कहना है कि **New Maintenance Policy 2018** योजनान्तर्गत चल रहे पथ के निर्माणधीन कार्य के विरुद्ध चल रहे योजनाओं का भुगतान की आवश्यकता है। अधियाचना का निर्माण कार्य विशिष्टियों के अनुरूप है तथा कार्य संतोषप्रद है।

अतः अनुरोध है कि अधियाचना पत्र के आधार पर आवंटन उपलब्ध कराने की कृपा की जाय।

अनु०- 1) अधियाचना प्रपत्र।

2) 19ए फॉर्म।

विश्वासभाजन

14/11/24

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, दलसिंहसराय

Rural Works Department, Works Division Dalsinghsarai
Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018
(Initial Rectification and Surface Renewal)

Name of Division : PU(Dalsinghsarai)

Sl No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Length (in Km)	Amount (in Lac)	Initial Rectification with Surface Renewal (in lac)	5 years Routine Maintenance (in lac)	Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of (in mm km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (1 Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1		L063-nb-103 to Ravasavda (VR63)	32010412086	6120/04.12.23	1.67	82.18	60.58774	14.35100			-	3624	25mm	5.10%	51.49958	51.49958	9.07570	
2		NH103 - Rampur	32010412028	6120/04.12.23	3.99	185.74	134.62938	34.69902			-	3242	25mm	5.10%	114.43497	114.43497	20.17692	
3		T04 hantachampur to mustar tola	32010413030	6120/04.12.23	0.89	53.386	42.57722	6.36880			-	3243	25mm	5.10%	36.19064	36.19064	6.25346	
4		L056-NH1 to Uttar Tola via dajagan	32010412129	6120/04.12.23	1.505	67.546	47.80426	13.52237			-	3563	25mm	5.10%	40.63362	40.63362	7.04265	
5		NH-28 to Mubharapur	32010413036	6120/04.12.23	1.185	67.735	53.09348	9.35002			-	3561	25mm	5.10%	45.12946	45.12946	7.85316	
6		L042 to haryan tola	32010413024	6120/04.12.23	1.08	58.618	44.67659	8.52900			-	3525	25mm	5.10%	0.00000	0.00000	44.65997	
7		T02 to kankalipur	32010412030	6120/04.12.23	1.14	63.78	48.41612	9.21981			-	3479	25mm	5.10%	0.00000	0.00000	48.27890	
8		L028 to Mathuram	32010414005	6120/04.12.23	1.15	68.884	53.66011	8.73411			-	3536	25mm	5.10%	0.00000	0.00000	53.65681	
9		T04 to haryan Mustar Tola	32010413037	6120/04.12.23	0.575	27.375	19.83838	4.88342			-	3713	25mm	5.10%	0.00000	0.00000	19.80104	
TOTAL															287.888	287.888	216.79773	

- Signed Hard Copy and Soft Copy (in Excel) of recorded JRI is enclosed
- Up-to date Physical Progress has been uploaded in MIS.

Divisional Account Officer,
Rural Works Department,
Works Division Dalsinghsarai

[Signature]

[Signature]

Executive Engineer,
Rural Works Department,
Works Division Dalsinghsarai

[Signature]

FROM GFR-19-A

(See Govt. of India's decision(i) below rule 150)

Form of Utilisation Certificate upto Nov- 2024

New Maintenance Policy 2018(MR New)

PIU:- RWD Works Division Dalsinghsarai

Sl No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lakh)	Amount Received (in Lakh)	Particulars
1	2	3	4	5
1	New Maintenance Policy 2018 (MR New)	11414.16369	11414.16369	Certified that out of Rs-11414.16369 Lakh Received till date in favour of Executive Engineer, RWD Works Division Dalsinghsarai a Sum of Rs-11392.90290 Lakh has been utilized for the New Maintenance Policy 2018 (MR New) Scheme as given in the margine for which it was Sanctioned and that the Balance of Rs-21.26079 Lakh remaining unutilized at the end of period under the time of completion
		11414.16369	11414.16369	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was

Kind of Checks Exercised:-

- (i) Workers have been supervised by Executive Engineer/ Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- (iii) Construction materials have been tested
- (iv) Measurments have been recorded in the MB's and test check conducted by the
- (v) All other codal formalities have overserved

3. Physical Progress Achieved

- (i) Construction of Road Works
- (ii) Construction of CD Works


14/11/2024
DAO

Rural Works Department,
Works Division Dalsinghsarai


14/11/24
Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, दलसिंहसराय
प्रतिवेदन

क्र०सं०	शर्त	अभ्युक्ति
1	मापी पुस्त पर इस आशय का प्रमाण पत्र दर्ज है कि कार्य गुणवत्ता पूर्ण कराया गया है एवं विशिष्टियों के अनुरूप है।	T02 to kankalipur का निर्माण कार्य गुणवत्ता पूर्ण कराया गया है एवं विशिष्टियों के अनुरूप है।
2	कराये गये कार्यों के सभी अवयवों के अवयववार 100 प्रतिशत कार्य का दर्ज मापी का सत्यापन कनीय अभियंता, कम से कम 50 प्रतिशत मापी का सत्यापन सहायक अभियंता एवं कम से कम 10 प्रतिशत मापी का सत्यापन कार्यपालक अभियंता द्वारा किये जाने का प्रमाण – पत्र को विभागीय MIS पर अपलोड जाय।	T02 to kankalipur का कराये गये कार्यों के सभी अवयवों के अवयववार मापी का सत्यापन कनीय अभियंता, सहायक अभियंता एवं कार्यपालक अभियंता द्वारा किया गया है।

[Signature]
14/11/24

कनीय अभियंता
 ग्रामीण कार्य विभाग
 कार्य प्रमंडल, सरायरंजन


[Signature]
14/11/24

सहायक अभियंता
 ग्रामीण कार्य विभाग
 कार्य प्रमंडल, सरायरंजन

[Signature]
14/11/24

कार्यपालक अभियंता
 ग्रामीण कार्य विभाग
 कार्य प्रमंडल, दलसिंहसराय

Name of Customer: Bhagwati Construction, Machine no: 19192, Road: T02 to kankalpur, Date: 14-11-24, Section No: 04, Equation: $Y=0.839X+355$



PA
14/11/24
HLS

PA
14/11/24
HLS

PA
14/11/24
HLS

Name of the work: T02 to kankalipur

Date	Time	Test No	Distance (meter)	Total Distance (meter)	BUMP (cm)	Speed (km/hr)	UI(mm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction	Remarks
14-11-2024	15:51:11	4	100	100	19.0 cm	12.6 Km/H	1900.0 mm/Km	2044.1	2.86	Good	25.780318	N	85.800392	E	Normal
14-11-2024	15:51:54	4	100	200	21.0 cm	13.2 Km/H	2100.0 mm/Km	2221.9	3.081	Good	25.779827	N	85.820274	E	Normal
14-11-2024	16:52:34	4	100	300	22.0 cm	14.8 Km/H	2200.0 mm/Km	2310.8	3.191	Good	25.778837	N	85.820041	E	Normal
14-11-2024	15:52:51	4	100	400	21.0 cm	21.8 Km/H	2100.0 mm/Km	2221.9	3.081	Good	25.778664	N	85.818961	E	Normal
14-11-2024	15:53:07	4	100	500	29.0 cm	22.2 Km/H	2900.0 mm/Km	2933.1	3.948	Good	25.778689	N	85.817036	E	Normal
14-11-2024	15:53:31	4	100	600	27.0 cm	15.3 Km/H	2700.0 mm/Km	2755.3	3.734	Good	25.778582	N	85.816145	E	Normal
14-11-2024	15:53:55	4	100	700	29.0 cm	17.0 Km/H	2900.0 mm/Km	2933.1	3.948	Good	25.778533	N	85.815377	E	Normal
14-11-2024	15:54:15	4	100	800	26.0 cm	17.4 Km/H	2600.0 mm/Km	2666.4	3.626	Good	25.778214	N	85.814547	E	Normal
14-11-2024	15:54:36	4	100	900	24.0 cm	15.4 Km/H	2400.0 mm/Km	2488.6	3.41	Good	25.777559	N	85.813902	E	Normal
14-11-2024	15:54:57	4	100	1000	25.0 cm	17.1 Km/H	2500.0 mm/Km	2577.5	3.518	Good	25.777427	N	85.813119	E	Normal
14-11-2024	15:55:17	4	100	1100	29.0 cm	18.3 Km/H	2900.0 mm/Km	2933.1	3.948	Good	25.776945	N	85.812299	E	Normal
14-11-2024	15:55:36	4	100	1200	24.0 cm	18.8 Km/H	2400.0 mm/Km	2488.6	3.41	Good	25.776015	N			
													IRI Value		3479
													Machine ID		19192

14/11/24
28

Bump
14/11/24
AGE

14/11/24