

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD Works Division Trivenigam

Name of Block Road :- Chhatapur / Chhatapur Laxmipur sima se khatbe Talu Motadit talg khunt TK.

A. For Road

1. Damage Location/Chainage :- At - Ch. 400 M, 570 M, 612 M

2. Damage Length :- 133 M

3. Nature of Damage (Length Wise) (i) Breach :- Fully Breach at same Location.

(ii) Crust Damage :-

(iii) Only Flank Damage :-

whether traffic fully/Partialiy obstructed :- Traffic fully obstructed.

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick Bats EC Bag, Bamboo, H.P, ETC.

(ii) Equipment/Tools Being Used in Restoration Works :- J.C.B, Tractor etc.

(iii) Restored Length - 133 M

In open Area :-

In habitation Area :- 133 M

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-

Satisfactory

SW
11/11/24

11/11/24

Signature of Inspector
Executive Engineer
(Official Seal)
Road Works Department
Work's Division, Supaul