

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- RWD, Works Division - Supaul

Name of Block Road :- Kishanpur/L040 Tharbitiya to Digliya Yadav Tola.

A. For Road

1. Damage Location/Chainage :- Pigganj, Maujaha etc. at CH:- 3.0 km CH:- 3 to 4 km
at CH:- 2.5 to 3.0 km, etc.

2. Damage Length :- 1122 M

3. Nature of Damage (Length Wise) (i) Breach :- Fully Breached

(ii) Crust Damage :-

(iii) Only Flank Damage :-

whether traffic fully/Partially obstructed :- Fully obstructed.

4. Details of Restoration :-

(i) Material Being Used in Restoration :- EC Bags, N.C., Local Sand, Brick Bats, Bamboo etc.

(ii) Equipment/Tools Being Used in Restoration Works :- JCB, Tractor, Dumper, Roller, Jet Machine etc.

(iii) Restored Length 1122 M

In open Area :- 1122 M

In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert) N.A.

(1) Damage Location/Chainage :- N.A.

(2) No. of Span Damage :- N.A.

(3) Length of Span :- N.A.

(4) Nature of Damage (Pier/Abutment/

Wing Wall/Approach Road Damage) :- Approach Road Damaged.

(5) Details of Restoration :-

(i) Material Being Used in Restoration :- Bamboo, EC Bags, Local Sand, etc.

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor, Jet Machine, JCB etc.

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

Aman Raj
14/11/24

JP
14/11/2024
A.E

Signature of Inspector

(Official Seal)

Executive Engineer
Rural Works Department
Works Division Udakishunganj