

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :-		RWA, Works Division, Khatlgan.	
Name of Block / Road :-		Pirpani / Gopali Chauri Bhangad to Tiani tola via Huzur Nagar Sanwali tola P.O.	
A. For Road			
1. Damage Location / Chainage :		Ch:- 5-500m.	
2. Damage Length :		47.4 m	
3. Nature of Damage (length wise)		(i) Breach :- —	
		(ii) Crust Damage :- 47.4 m	
		(iii) Only Flank Damage —	
whether traffic fully/Partialily obstructed		— Fully obstructed.	
4. Details of Restoration ;			
(i) Material Being Used in Restoration : Brick bats, Sand bags, Stone screenings,			
(ii) Equipment / Tools being Used in Restoration Works : Front end loader, smooth wheel roller.			
(iii) Restored length		In open Area :- 47.4 m.	
		In habitation Area :- —	
(iv) if Restoration work done in habitation Area give Reason :- —			
B. For Bridge (Size of Bridge / Culvert) — NA —			
1. Damage Location / Chainage :		— NA —	
2. No. of Span Damage :-		— NA —	
3 Length of Span		— NA —	
4 Nature of Damage (Pier / Abutment/Wing wall/Approach Road Damage) — NA —			
5. Details of Restoration : —			
(i) Material Being Used in Restoration : —			
(ii) Equipment / Tools being Used in Restoration Works : —			
(iii) Restored length		In open Area :- —	
		In habitation Area :- —	
Overall Grade of Restoration Work (Satisfactory / Unsatisfactory) Satisfactory			

12.11.24
AE

Signature
12/11/24
Signature of Engineer
R.W.D. W.D. Naugachia
(Official Seal)