

## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- ER. AJAY KUMAR (EE, RWD, CHAKIA)	
Name of Block/Road :- CHAKIA / Amor Kishore Singh house to Nanak Ran house	
<b>A. For Road</b>	
1. Damage Location/Chainage :- 300M	
2. Damage Length :- 49M	
3. Nature of Damage (Length Wise)	(i) Breach :- 7M
	(ii) Crust Damage :- 42M
	(iii) Only Flank Damage :-
whether traffic fully/Partialy obstructed :- Fully obstructed	
<b>4. Details of Restoration :-</b>	
(i) Material Being Used in Restoration :- Hume Pipe, Brick bats, Bamboos	
(ii) Equipment/Tools Being Used in Restoration Works :- JCB, Tractor	
(iii) Restored Length	In open Area :- 49M
	In habitation Area :-
(iv) If Restoration work done in habitation Area give Reason :-	
<b>B. For Bridge (Size of Bridge/Culvert)</b>	
(1) Damage Location/Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttment/ Wing Wall/Approach Road Damage) :-	
(5) Details of Restoration :-	
(i) Material Being Used in Restoration :-	
(ii) Equipment/Tools Being Used in Restoration Works :-	
(iii) Restored Length :-	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory	

J. Kumar

14.11.2024  
AE

Signature of Inspector  
(Official Seal)  
Executive Engineer  
R.W.D. (W.D.)  
Araaj