

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- Er. Manoj Kumar, Works Division, Purni

Name of Block / Road :- Sursand / PMGSY Sondahi to Sonahitalg.

A. For Road

1. Damage location / Chainage :- ch. 200m, ch. 250m, ch. 280m, ch. 300m, ch. 330m, ch. 350m.

2. Damage Length :- 151 m.

3. Nature of Damage (Length Wise)

(i) Breach :- 151 m.

(ii) Crust Damage :-

(iii) Only Flank Damage

Whether Traffic Fully / Partially obstructed :- Fully obstructed.

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick Bed, Rabbitch.

(ii) Equipment / Tools Being used in Restoration Work :- JCB, Roller & tractor.

(iii) Restored Length

In open Area :-

In Habitation Area :-

(iv) If Restoration Work Done in habitation Area give Reason :-

B. For Bridge (Size of Bridge / Culvert)

(1) Damage Location / Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/ Approach Road Damage) :-


(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment / Tools Being used in Restoration Work :- JCB, Roller, tractor

(iii) Restored Length

Overall Grade of restoration Work (Satisfactory/Unsatisfactory) :- Satisfactory.


 19/11/24
 Signature of Inspector
 (Official Seal)