

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- Er. Manoj Kumar, Works Division, Puri.

Name of Block / Road :- Surasand / Rampadesth Ray house to kailash Ray house
Sondahi 6044.

A. For Road

1. Damage location / Chainage :- Ch. → 30 M , Ch. → 45 M.

2. Damage Length :- 28 M.

3. Nature of Damage (Length Wise)
(i) Breach :- 28 M.
(ii) Crust Damage :-
(iii) Only Flank Damage

Whether Traffic Fully / Partially obstructed :- Fully obstructed.

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick Battis Rabbish.

(ii) Equipment / Tools Being used in Restoration Work :- JCB, Roller & tractor.

(iii) Restored Length
In open Area :-
In Habitation Area :-

(iv) If Restoration Work Done in habitation Area give Reason :- NA.

B. For Bridge (Size of Bridge / Culvert)

(1) Damage Location / Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/ Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment / Tools Being used in Restoration Work :- JCB, Roller & tractor.

(iii) Restored Length

Overall Grade of restoration Work (Satisfactory/Unsatisfactory) :- Satisfactory.

Ami
19/11/24
Signature of Inspector
(Official Seal)