

# INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E.E. RWD works Division, Beland  
Name of Block / Road :- Baradik to Ramnagar under Ramnaisaidpur  
Block

## A. For Road

1. Damage location / Chainage :- 26.427865; 85.438049

2. Damage Length :- 0.535 km

3. Nature of Damage ( Length Wise)

(i) Breach :- 0.072 km

(ii) Crust Damage :- 0.463 km

(iii) Only Flank Damage

Whether Traffic Fully / Partially obstructed :-

Fully obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :-

Brick bats, Rubbish

(ii) Equipment / Tools Being used in Restoration Work :-

JCB, Tractor, Roller

(iii) Restored Length

In open Area :- 0.535 km

In Habitation Area :-

(iv) If Restoration Work Done in habitation Area give Reason :-

## B. For Bridge (Size of Bridge / Culvert )

(1) Damage Location / Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage ( Pier/Abutment/  
Wing Wall/ Approach Road Damage ) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment / Tools Being used in Restoration Work :-

(iii) Restored Length

Overall Grade of restoration Work ( Satisfactory/Unsatisfactory) :-

Satisfactory

Signature of Inspector  
(Official Seal)  
Executive Engineer  
Rural Works Department  
Works Division, Sheohar