

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- R.W.D. Works Division Kamalganj

Name of Block / Road :- 2097 PMGSY Atharia Ramdaspur Road to Kamalganj

For Road

Damage Location / Chainage : Ch:- 0.080 km, Ch:- 0.500 km, Ch:- 0.800 km

Damage Length : 101.6 m

Nature of Damage (length wise) (i) Breach :- 92.1 m.

(ii) Crust Damage :- 9.5 m

(iii) Only Flank Damage

Whether traffic fully/Partialily obstructed - Fully obstructed.

Details of Restoration ;

i) Material Being Used in Restoration : Brick ball, Stone Screwing, 1000mm MP3 Pipe

ii) Equipment / Tools being Used in Restoration Works : Front end loader, Roller

iii) Restored length

In open Area :- 92.10 m.

In habitation Area :-

(iv) if Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge / Culvert)

1. Damage Location / Chainage :

2. No. of Span Damage :-

3 Length of Span

4 Nature of Damage (Pier / Abutment/Wing wall/Approach Road Damage)

5. Details of Restoration :

(i) Material Being Used in Restoration :

(ii) Equipment / Tools being Used in Restoration Works :

(iii) Restored length

In open Area :-

In habitation Area :-

Overall Grade of Restoration Work (Satisfactory / Unsatisfactory) Satisfactory

Signature
12-11-24
de

Signature of Inspector
12/11/24
Executive Engineer
(Official Seal)
R. W. D., W. D. Naugachia