

INSPECTION REPORT FOR MOTORABLE WORK

Name of PUs :-		Rwa Ward Division, Kalyan.	
Name of Block / Road :-		Pimpri / Kalyan - to Kalyan	
A. For Road			
1. Damage Location / Chainage :-		Ch:- 0.200 Km	
2. Damage Length :-		70.10 m	
3. Nature of Damage (length wise)		(i) Breach :-	29.80 m
		(ii) Crust Damage :-	40.3 m.
		(iii) Only Flank Damage	—
whether traffic fully/Partially obstructed — Fully obstructed.			
4. Details of Restoration ;			
(i) Material Being Used in Restoration : — Bricks bats, Stone Screwing.			
(ii) Equipment / Tools being Used in Restoration Works : Front End loader, Roller.			
(iii) Restored length		In open Area :-	70.10 m.
		In habitation Area :-	—
(iv) if Restoration work done in habitation Area give Reason :- —			
B. For Bridge (Size of Bridge / Culvert)			
1. Damage Location / Chainage :-		—	
2. No. of Span Damage :-		—	
3 Length of Span		—	
4 Nature of Damage (Pier / Abutment/Wing wall/Approach Road Damage)		—	
5. Details of Restoration :-		—	
(i) Material Being Used in Restoration :-		—	
(ii) Equipment / Tools being Used in Restoration Works :-		—	
(iii) Restored length		In open Area :-	—
		In habitation Area :-	—
Overall Grade of Restoration Work (Satisfactory / Unsatisfactory) Satisfactory.			

12-11-24

Signature of Inspector
(Official Seal)
Executive Engineer
W. D. Naugachia