

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- RWD Work division kahalgaon	
Name of Block / Road :- Sabour, Shivayadih Village to Rajpur Murhan Path.	
A. For Road	
1. Damage Location / Chainage : — N/A —	
2. Damage Length : — N/A —	
3. Nature of Damage (length wise)	(i) Breach :- — N/A —
	(ii) Crust Damage :- — N/A —
	(iii) Only Flank Damage — N/A —
whether traffic fully/Partialily obstructed	
4. Details of Restoration ; — N/A —	
(i) Material Being Used in Restoration : — N/A —	
(ii) Equipment / Tools being Used in Restoration Works : — N/A —	
(iii) Restored length	In open Area :- — N/A —
	In habitation Area :- — N/A —
(iv) if Restoration work done in habitation Area give Reason :-	
B. For Bridge (Size of Bridge / Culvert)	
1. Damage Location / Chainage :	
2. No. of Span Damage :-	
3 Length of Span	
4 Nature of Damage (Pier / Abutment/Wing wall/Approach Road Damage)	
5. Details of Restoration :	
(i) Material Being Used in Restoration : Brick bats, E.C bags, Bamboo Pelling.	
(ii) Equipment / Tools being Used in Restoration Works : Tractor, Front end loader, Roller.	
(iii) Restored length	In open Area :- ✓
	In habitation Area :- — N/A —
Overall Grade of Restoration Work (Satisfactory / Unsatisfactory) Satisfactory.	

Signature
12/11/24
Signature of Inspector
(Official Seal)