

कार्यपालक अभियन्ता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, हथुआ।

पत्रांक— **1378**

दिनांक— **15-11-2024**

प्रेषक,

कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, हथुआ।

सेवा में,

सचिव,
बिहार, ग्रामीण पथ विकास अभिकरण,
बिहार, पटना।

विषय :— बिहार ग्रामीण पथ नई अनुरक्षण नीति-2018 के तहत क्रियान्वित पथ मरम्मत कार्य हेतु राशि उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषयक बिहार ग्रामीण पथ नई अनुरक्षण नीति-2018 के तहत क्रियान्वित पथ मरम्मत कार्य हेतु राशि की अधियाचना विहित प्रपत्र में की जा रही है।

अतः भवदीय से अनुरोध है कि कॉलम 18 में अंकित राशि उपलब्ध कराने की कृपा की जाय।

अनु०— यथोक्त।

विश्वासभाजन,



15.11.24

कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, हथुआ।

Requisition Format for Scheme Head- MR (3054) under Bihar Rural Road Maintenance Policy- 2018 (Initial Rectification and Surface Renewal)																			
Name of Works Division :- Rural Works Department, Works Division Hathua.																			
Sl No.	Package No.	Name of Road	Project ID as Per MIS	Administrative Approval (AA) Letter No & Date.	Administrative Approval (AA)		Agreement Amount (In Lakh)			Agreement No & Date	Date & Completion as per Agreement.	Actual Date of Completion	Value of IRI (In MM/KM)	Thickness of Bitumen layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allotted Amount (In Lakh)	Up-to date expenditure as per MIS (In Lakh)	Requisition against work done, (In Lakh)	Remarks
					Length (In Lakh)	Amount (In Lakh)	Initial Rectification with surface Renewal (In Lakh)	5 Year Routine Maintenance (In Lakh)											
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	MR-N/23-24/Hathua/-11	L041-Kalyanpur to Nadwan (VR21)	31407102047	Letter-1086, Dt-01.03.2024	5.800	128.770	198.53463	39.04699	08/MBD/2024-25 Date-10.09.2024	09.06.2025	-	Good	25	5.00	0.00000	0.00000	191.50000	Surface Complete	
					5.800	128.770	198.53463	39.04699							0.00000	0.00000	191.50000		

प्रमाणित किया जाता है कि पथ में कराये गये कार्य मानक एवं विशिष्टियों के अनुरूप है।


J.E
Bhore

J.E
Bhore


D.A.O
R.W.D Works Division, Hathua.

D.A.O
R.W.D Works Division, Hathua.


15.11.24
Executive Engineer,
R.W.D Works Division, Hathua.

Executive Engineer,
R.W.D Works Division, Hathua.

FORM GFR 19 - A

(See Government of India's Decision (1) below Rule - 150)

Form utilisation Certificate up to the month of Up to 31.10.2024

MR-3054 (New Maintenance Policy-2018)

RWD Works Division - HATHUA

1	Head	Amount Received		Expenditure		Balance	
		IN A/C-	0.00	IN A/C-	0.00	IN A/C-	0.00
		By CFMS-	1213172768.00	By CFMS-	1213158273.00	By CFMS-	14495.00
		Total-	1213172768.00	Total-	1213158273.00	Total-	14495.00
	MR-3054 (New Maintenance Policy-2018)					Certified that sum of Rs 12131.58 Lac has been utilized for the purpose of MR-3054 (New Maintenance Policy-2018) Schemes as given in the margin for which it was sanctioned and that the balance of Rs 0.14495 Lac Lacs remaining utilized at the end of the period under.	

2. Certified that I have satisfied myself that the conditions on which the grants-in aid was sanctioned have been duly

Kind of Checks exercised :-

- (i) Works have been supervised by Executive Engineer/Superintending Engineer.
- (ii) Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- (iii) Construction material have been tested.
- (iv) Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- (v) All other codal formalities have been observed.


3. Physical Progress achieved :-

- (i) Construction of Road Works.
- (ii) Construction of CD Works



D.A.O

Rural Works Department
Works Division Hathua



15.11.24

Executive Engineer
Rural Works Department
Works Division Hathua

Name of work : L041-Kalyanpur to Nadwan (VR21)

Name of customer : M/S Pawan Construction

(R)Rural Road

Good	Average	Poor
< 4000	4001 - 5000	> 5000

Date	Time	Test No	Distance(m)	Total Distance(m)	BUMP(cm)	Speed(Km/Hr)	U/I(mm/Km)	Corrected U/I (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
15/11/24	16:39:17	114	0	0	0.0 cm	0.0 Km/Hr	0.0 mm/Km	245	0.43	Good	26.4068117	N	84.2004404	E	Normal
15/11/24	16:40:28	114	100	100	23.0 cm	13.7 Km/Hr	2300.0 mm/Km	2398	3.3	Good	26.4800959	N	84.1756678	E	Normal
15/11/24	16:40:59	114	100	200	27.0 cm	11.7 Km/Hr	2700.0 mm/Km	2773	3.75	Good	26.4802790	N	84.1746912	E	Normal
15/11/24	16:41:25	114	100	300	26.0 cm	13.7 Km/Hr	2600.0 mm/Km	2679	3.64	Good	26.4803762	N	84.1739435	E	Normal
15/11/24	16:42:00	114	100	400	29.0 cm	10.2 Km/Hr	2900.0 mm/Km	2960	3.98	Good	26.4808435	N	84.1729517	E	Normal
15/11/24	16:42:22	114	100	500	23.0 cm	16.2 Km/Hr	2300.0 mm/Km	2398	3.3	Good	26.4812841	N	84.1719751	E	Normal
15/11/24	16:42:44	114	100	600	28.0 cm	16.3 Km/Hr	2800.0 mm/Km	2866	3.87	Good	26.4807920	N	84.1715631	E	Normal
15/11/24	16:43:06	114	100	700	22.0 cm	16.6 Km/Hr	2200.0 mm/Km	2305	3.18	Good	26.4797583	N	84.1712732	E	Normal
15/11/24	16:43:27	114	100	800	29.0 cm	16.2 Km/Hr	2900.0 mm/Km	2960	3.98	Good	26.4799242	N	84.1704798	E	Normal
15/11/24	16:43:44	114	100	900	20.0 cm	22.0 Km/Hr	2000.0 mm/Km	2117	2.95	Good	26.4800215	N	84.1695842	E	Normal
15/11/24	16:43:59	114	100	1000	26.0 cm	23.8 Km/Hr	2600.0 mm/Km	2679	3.64	Good	26.4801245	N	84.1684427	E	Normal
15/11/24	16:44:13	114	100	1100	21.0 cm	24.9 Km/Hr	2100.0 mm/Km	2211	3.07	Good	26.4804773	N	84.1674814	E	Normal
15/11/24	16:44:27	114	100	1200	27.0 cm	24.9 Km/Hr	2700.0 mm/Km	2773	3.75	Good	26.4807215	N	84.1667032	E	Normal
15/11/24	16:44:41	114	100	1300	24.0 cm	26.7 Km/Hr	2400.0 mm/Km	2492	3.41	Good	26.4810762	N	84.1656427	E	Normal
15/11/24	16:45:15	114	100	1400	28.0 cm	13.5 Km/Hr	2800.0 mm/Km	2866	3.87	Good	26.4815435	N	84.1650248	E	Normal
15/11/24	16:46:00	114	100	1500	27.0 cm	18.0 Km/Hr	2700.0 mm/Km	2773	3.75	Good	26.4824400	N	84.1651392	E	Normal
15/11/24	16:46:20	114	100	1600	26.0 cm	17.6 Km/Hr	2600.0 mm/Km	2679	3.64	Good	26.4833593	N	84.1649713	E	Normal
15/11/24	16:46:42	114	100	1700	24.0 cm	16.3 Km/Hr	2400.0 mm/Km	2492	3.41	Good	26.4842005	N	84.1649408	E	Normal
15/11/24	16:46:57	114	100	1800	23.0 cm	23.1 Km/Hr	2300.0 mm/Km	2398	3.3	Good	26.4846773	N	84.1650095	E	Normal
15/11/24	16:47:16	114	100	1900	28.0 cm	19.0 Km/Hr	2800.0 mm/Km	2866	3.87	Good	26.4859705	N	84.1647119	E	Normal
15/11/24	16:48:15	114	100	2000	23.0 cm	16.4 Km/Hr	2300.0 mm/Km	2398	3.3	Good	26.4861898	N	84.1637506	E	Normal

R-2 P.1
15/11/24

[Signature]

15.11.24
Executive Engineer
R.W.D. Works Division
Hathua

Name of work : L041-Kalyanpur to Nadwan (VR21)

Name of customer : M/S Pawan Construction

(R)Rural Road

Good			Average			Poor									
< 4000			4001 - 5000			> 5000									
15/11/24	16:49:10	114	100	2100	20.0 cm	16.6 Km/Hr	2000.0 mm/Km	2117	2.95	Good	26.4867201	N	84.1632471	E	Normal
15/11/24	16:50:41	114	100	2200	24.0 cm	13.9 Km/Hr	2400.0 mm/Km	2492	3.41	Good	26.4875326	N	84.1630564	E	Normal
15/11/24	16:51:20	114	100	2300	21.0 cm	19.0 Km/Hr	2100.0 mm/Km	2211	3.07	Good	26.4882460	N	84.1629877	E	Normal
15/11/24	16:51:42	114	100	2400	19.0 cm	15.5 Km/Hr	1900.0 mm/Km	2024	2.83	Good	26.4885092	N	84.1620111	E	Normal
15/11/24	16:51:55	114	100	2500	25.0 cm	26.4 Km/Hr	2500.0 mm/Km	2585	3.53	Good	26.4886980	N	84.1611032	E	Normal
15/11/24	16:52:09	114	100	2600	27.0 cm	25.7 Km/Hr	2700.0 mm/Km	2773	3.75	Good	26.4888105	N	84.1602259	E	Normal
15/11/24	16:52:26	114	100	2700	20.0 cm	22.2 Km/Hr	2000.0 mm/Km	2117	2.95	Good	26.4890871	N	84.1591501	E	Normal
15/11/24	16:52:42	114	100	2800	16.0 cm	22.2 Km/Hr	1600.0 mm/Km	1743	2.48	Good	26.4884577	N	84.1590052	E	Normal
15/11/24	16:53:07	114	100	2900	22.0 cm	14.8 Km/Hr	2200.0 mm/Km	2305	3.18	Good	26.4875936	N	84.1586237	E	Normal
15/11/24	16:53:27	114	100	3000	23.0 cm	17.3 Km/Hr	2300.0 mm/Km	2398	3.3	Good	26.4884043	N	84.1582727	E	Normal
15/11/24	16:53:44	114	100	3100	19.0 cm	21.6 Km/Hr	1900.0 mm/Km	2024	2.83	Good	26.4884443	N	84.1573725	E	Normal
15/11/24	16:53:57	114	100	3200	18.0 cm	26.2 Km/Hr	1800.0 mm/Km	1930	2.72	Good	26.4882822	N	84.1564112	E	Normal
15/11/24	16:54:10	114	100	3300	11.0 cm	28.2 Km/Hr	1100.0 mm/Km	1275	1.88	Good	26.4885511	N	84.1553888	E	Normal
15/11/24	16:54:25	114	100	3400	20.0 cm	24.3 Km/Hr	2000.0 mm/Km	2117	2.95	Good	26.4883432	N	84.1547174	E	Normal
15/11/24	16:54:39	114	100	3500	23.0 cm	26.1 Km/Hr	2300.0 mm/Km	2398	3.3	Good	26.4873781	N	84.1544580	E	Normal
15/11/24	16:54:53	114	100	3600	29.0 cm	24.9 Km/Hr	2900.0 mm/Km	2960	3.98	Good	26.4866343	N	84.1541224	E	Normal
15/11/24	16:55:18	114	100	3700	21.0 cm	14.8 Km/Hr	2100.0 mm/Km	2211	3.07	Good	26.4856405	N	84.1539698	E	Normal
15/11/24	16:55:42	114	100	3800	25.0 cm	15.4 Km/Hr	2500.0 mm/Km	2585	3.53	Good	26.4847136	N	84.1540842	E	Normal
15/11/24	16:56:13	114	100	3900	22.0 cm	11.3 Km/Hr	2200.0 mm/Km	2305	3.18	Good	26.4839773	N	84.1542673	E	Normal
15/11/24	16:56:32	114	100	4000	29.0 cm	19.2 Km/Hr	2900.0 mm/Km	2960	3.98	Good	26.4840212	N	84.1551752	E	Normal
15/11/24	16:57:04	114	100	4100	24.0 cm	11.3 Km/Hr	2400.0 mm/Km	2492	3.41	Good	26.4841757	N	84.1559610	E	Normal
15/11/24	16:57:35	114	100	4200	23.0 cm	11.6 Km/Hr	2300.0 mm/Km	2398	3.3	Good	26.4840307	N	84.1569529	E	Normal

[Signature]

15.11.24

Executive Engineer
R.W.D. Works Division
Hathua

[Signature]
15.11.24

Name of work : L041-Kalyanpur to Nadwan (VR21)

Name of customer : M/S Pawan Construction

(R)Rural Road			
Good		Average	Poor
< 4000		4001 - 5000	> 5000


15/11/24	16:58:02	114	100	4300	23.0 cm	12.9 Km/Hr	2300.0 mm/Km	2398	3.3	Good	26.4835577	N	84.1577845	E	Normal
15/11/24	16:58:29	114	100	4400	28.0 cm	13.5 Km/Hr	2800.0 mm/Km	2866	3.87	Good	26.4830408	N	84.1583033	E	Normal
15/11/24	16:58:48	114	100	4500	29.0 cm	18.8 Km/Hr	2900.0 mm/Km	2960	3.98	Good	26.4823084	N	84.1583643	E	Normal
15/11/24	16:59:02	114	100	4600	12.0 cm	24.4 Km/Hr	1200.0 mm/Km	1368	2	Good	26.4814424	N	84.1582727	E	Normal
15/11/24	16:59:16	114	100	4700	17.0 cm	25.7 Km/Hr	1700.0 mm/Km	1836	2.6	Good	26.4805479	N	84.1582193	E	Normal
15/11/24	16:59:33	114	100	4800	19.0 cm	22.2 Km/Hr	1900.0 mm/Km	2024	2.83	Good	26.4800253	N	84.1587229	E	Normal
15/11/24	16:59:50	114	100	4900	18.0 cm	21.6 Km/Hr	1800.0 mm/Km	1930	2.72	Good	26.4795141	N	84.1594706	E	Normal
15/11/24	17:00:08	114	100	5000	17.0 cm	20.4 Km/Hr	1700.0 mm/Km	1836	2.6	Good	26.4796152	N	84.1604700	E	Normal
15/11/24	17:00:30	114	100	5100	24.0 cm	16.3 Km/Hr	2400.0 mm/Km	2492	3.41	Good	26.4791765	N	84.1611185	E	Normal
15/11/24	17:01:11	114	100	5200	22.0 cm	18.7 Km/Hr	2200.0 mm/Km	2305	3.18	Good	26.4787321	N	84.1616907	E	Normal
15/11/24	17:01:44	114	100	5300	22.0 cm	10.4 Km/Hr	2200.0 mm/Km	2305	3.18	Good	26.4790010	N	84.1624689	E	Normal
15/11/24	17:02:08	114	100	5400	26.0 cm	15.3 Km/Hr	2600.0 mm/Km	2679	3.64	Good	26.4794359	N	84.1631021	E	Normal
15/11/24	17:03:12	114	100	5500	28.0 cm	15.6 Km/Hr	2800.0 mm/Km	2866	3.87	Good	26.4803915	N	84.1634760	E	Normal
15/11/24	17:03:37	114	100	5600	26.0 cm	14.7 Km/Hr	2600.0 mm/Km	2679	3.64	Good	26.4804773	N	84.1644373	E	Normal
15/11/24	17:04:20	114	100	5700	28.0 cm	18.5 Km/Hr	2800.0 mm/Km	2866	3.87	Good	26.4811201	N	84.1650248	E	Normal
15/11/24	17:04:54	114	100	5800	24.0 cm	19.8 Km/Hr	2400.0 mm/Km	2492	3.41	Good	26.4809465	N	84.1659021	E	Normal

[Handwritten signature]
15.11.24

[Handwritten signature]
15.11.24

Executive Engineer
R.W.D. Works Division
Hathua

Name of Customer: M/S Pavan Construction , Machine no: 19193 , Road: L041-Kalyanpur to Nadwan (VR21) , Date: 15-11-24 , Section No: 114 , Equation: $Y=0.936X+245.3$



[Signature]

15-11-24

Executive Engineer
R.W.D. Works Division
Hathua

[Signature]
15-11-24