

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल- बक्सर

पत्रांक- 2461/बक्सर

दिनांक- 15/11/2024

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल- बक्सर

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण (BRRDA)
बुद्ध मार्ग, पटना।

विषय- शीर्ष 3054 (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) योजना अंतर्गत राशि की अधियाचना के सम्बन्ध में।


महाशय,

उपर्युक्त विषय के सम्बन्ध में कहना है कि योजना शीर्ष 3054 मरम्मति (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) अंतर्गत कराये गए कार्यों के भुगतान हेतु राशि की आवश्यकता है जिसे अधियाचना प्रपत्र के साथ सलग्न कर भेजा जा रहा है।

अतः श्रीमान से अनुरोध है कि सलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाए ताकि संवेदकों द्वारा कराये गए कार्य का भुगतान किया जा सके।

अनु०- यथोक्त

विश्वासभाजन


कार्यपालक अभियंता
ग्रा०का०वि०, कार्य प्रमंडल- बक्सर

AK
15/11/24

FORM GFR 19-A
(SEE Government of India's Decision (I) below Rule-150)
Form of Utilisation Certificate upto the month of Oct 2024

MR (3054) New Maintenance Policy 2018

TU - RWD (W), Div.- Buxar

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural Roads under MR (3054) Maintenance	Lt. No.- 115, dt.-23/10/2024	1189.36972	Certified that out of Rs. 1189.36972Lacs received during the years in favour of Ex. Engineer, RWD (W), Div.- Buxar Bihar, a sum of Rs 1189.36972 lacs has been utilized for the purpose of MR (3054) New Maintenance Policy 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs0.00 lacs remaining unutilized at the end of the period under.

Total -

- 2 Certified that I have satisfied myself that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-


- Works have been supervised by Executive Engineer/ Supertending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Supertending Engineer.
- Construction materials have been tested
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

3 Physical Progress achieved :-

- Construction of Road works
- Construction of CD works


15-11-24
Executive Engineer

R.W.D. (w) Div. Buxar


15/11/24

Requisition Format for Scheme Head- MR (3054) under Bihar Rural Road Maintenance Policy- 2018 (Initial Rectification and Surface Renewal)

Name of Works Division- RWD, Works Division- Buxar


Sl No	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No. & Date	Date Of Completion as per Agreement	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (In Lakh)	Up-to-date expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
					Length (in Km)	Amount (in Lakh)	Initial Rectification With Surface Renewal (In Lakh)	5 Years Routine Maintenance (In Lakh)									
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
3	RM/BU/BU X/23/0010	L088-T07 BARUPUR ROAD TO MARAHI (VR88)	10401902144	Letter No 6120 & 04/12/2023	1.403	64.427	28.61608	7.66024	02/MBD/2024-25 & 05.07.2024	04/04/2025	2879	25 mm	5.00%	0.0000	-	28.50475	
4	RM/BU/BU X/23/0010	Hakarpur village to middle school Soni village	14191033507	Letter No 6120 & 04/12/2023	2.350	100.529	46.62911	12.48116	02/MBD/2024-25 & 05.07.2024	04/04/2025	2895	25 mm	5.00%	0.0000	-	42.11671	
5	RM/BU/BU X/23/0010	(i) Itevan Hakarpur (Near Pool) - Khini Nadi Pool, (ii) Link Road of Itevan Hakarpur - Khini Nadi Po	NEA220002007	Letter No 6120 & 04/12/2023	1.530	73.076	32.92239	8.72811	02/MBD/2024-25 & 05.07.2024	04/04/2025	2920	25 mm	5.00%	0.0000	-	32.7293	


- Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed
- Up-to-date Physical Progress has been uploaded in MIS


15.11.24
7-E


15.11.24
Executive Engineer
RWD (W), Div.- Buxar

File : E:\ajeet kumar\narendra sasram\Itwan Hakarpur (Near Pool) - Khiri Nadi Poo\1611202401.Xls. Section No.
Name of Customer : Sanni Kumar. Name of Work/ Road : Itwan Hakarpur(Near Pool)-Khiri Nadi Pool, Link Road of




15.11.24
AE


15.11.24
AE


15.11.24
AE

Name of Road:-(i) Itwan Hakarpur (Near Pool) - Khiri Nadi Pool, (ii) Link Road of Itwan Hakarpur - Khiri Nadi Po Contractor Name :-Sanni Kumar									
Date	Time	Section	No.	Length in km	Bumps in mm	Rate	Speed mm/km	OR mm/km	IRI, TEGORY ROAD
15/11/24	12:49:0	28	0.1	260	10.1	2600	2789 G	25.33847	83.85855 Normal
15/11/24	12:50:44	28	0.1	290	10.1	2900	2941 G	25.3384	83.85866 Normal
15/11/24	12:52:0	28	0.1	270	10.1	2700	2896 G	25.33821	83.8587 Normal
15/11/24	12:52:30	28	0.1	290	10.1	2900	3285 G	25.33778	83.85956 Normal
15/11/24	12:53:41	28	0.1	320	10.1	3200	3285 G	25.33726	83.86024 Normal
15/11/24	12:55:0	28	0.1	280	10.1	2800	2945 G	25.33703	83.86157 Normal
15/11/24	12:56:2	28	0.1	310	10.1	3100	3245 G	25.33607	83.8632 Normal
15/11/24	12:58:0	28	0.1	330	10.1	3300	3256 G	25.33595	83.86352 Normal
15/11/24	12:59:32	28	0.1	220	10.1	2200	2341 G	25.33533	83.86446 Normal
15/11/24	13:4:0	28	0.1	280	10.1	2800	2912 G	25.33472	83.86583 Normal
15/11/24	13:4:50	28	0.1	250	10.1	2500	2689 G	25.33479	83.86629 Normal
15/11/24	13:5:0	28	0.1	240	10.1	2400	2654 G	25.33403	83.86706 Normal
15/11/24	13:5:0	28	0.1	310	10.1	3100	3282 G	25.33374	83.86753 Normal
15/11/24	13:5:59	28	0.1	270	10.1	2700	2768 G	25.33334	83.86979 Normal
15/11/24	13:6:60	28	0.1	220	10.1	2200	2356 G	25.33322	83.86853 Normal
15/11/24	13:6:45	28	0.03	250	10.1	2500	2687 G	25.33284	83.87119 Normal

Latitude Longitude Event

$$Y = 0 * X^2 + 0.816 * X + 249$$

$$X = 2789$$

$$Y = 2687$$

(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001

IRI Value=2895

Machine ID=415

15.11.24
715

15.11.24
AE

15.11.24