

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- R.W.D, Supaul

Name of Block Road :- Kishampur / 1053 - Abkhwar cross to/a to Navabhatla

A. For Road

1. Damage Location/Chainage :- At CH - 0.00 km to 4.00 km, CH - 4.00 to 5.00 km etc.

2. Damage Length :- 584.60 M

3. Nature of Damage (Length Wise) (i) Breach :- Fully Breached

(ii) Crust Damage :-

(iii) Only Flank Damage :-

whether traffic fully/Partially obstructed :- Fully obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :- EC Bags, Local Sand, Bricks Bats, Bamboo etc.

(ii) Equipment/Tools Being Used in Restoration Works :- JCB, Tractor, Dumper, Roller etc.

(iii) Restored Length 584.60 M

In open Area :- 584.60 M

In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

14/11/2024
A.E

Signature of Inspector
(Official Seal) Executive Engineer
Rural Works Department
Works Division Udakishungani