



## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- RKID, Jhargharpur	
Name of Block/Road :- Madhepur   Bihari Langraa chowk to Jhargharpur.	
<b>A. For Road</b>	
1. Damage Location/Chainage :- ch- 1.40 KM.	
2. Damage Length :- 140.80m	
3. Nature of Damage (Length Wise)	(i) Breach :- 140.80m
	(ii) Crust Damage :-
	(iii) Only Flank Damage :-
whether traffic fully/Partially obstructed :- Fully.	
4. Details of Restoration :-	
(i) Material Being Used in Restoration :- Brick bats.	
(ii) Equipment/Tools Being Used in Restoration Works :- JCB & Tractor.	
(iii) Restored Length	In open Area :- Open
	In habitation Area :- N.A
(iv) If Restoration work done in habitation Area give Reason :- N.A	
<b>B. For Bridge (Size of Bridge/Culvert)</b>	
(1) Damage Location/Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abutment/Wing Wall/Approach Road Damage) :-	
(5) Details of Restoration :-	
(i) Material Being Used in Restoration :-	
(ii) Equipment/Tools Being Used in Restoration Works :-	
(iii) Restored Length :-	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-	

  
 J.S.

  
**Executive Engineer**  
 Signature of Inspector  
 (Official Seal)  
 Division, Jhargharpur