

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- R.W.D, Supaul

Name of Block Road :- Kishanpur/Sujanpur to PMGSY Road

A. For Road

1. Damage Location/Chainage :-

At C.H = 0.400 K.M, 0.420 K.M, 0.470 K.M, 0.480 K.M --- 0.570 K.M etc

2. Damage Length :- 379.55 m

3. Nature of Damage (Length Wise)

(i) Breach :- fully breach

(ii) Crust Damage :-

(iii) Only Flank Damage :-

whether traffic fully/Partialiy obstructed :- fully obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brickbats etc.

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor, J.C.B etc.

(iii) Restored Length - 379.55 m.

In open Area :- 379.55 m

In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-

Satisfactory

14/11/2024
A.E

Signature of Inspector
(Official Seal) Executive Engineer
Rural Works Department
Works Division Udakishungani