

5th year maintenance bill

69

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W: Routine maintenance work for 5th year of road from Karmalor Gaj to Malbhar under NABARS at block K S.S. Road					
N/Aging - Dileep Kumar Verma					
App. No. - 01/SB.D/2018-19					
Actual date of completion - 10.02.2019					
Date of measurement - 06.04.2024					

Items of works.

① Restoration of rainwater/Bays with S.I.

16	2.40m	1.25m	0.30m	14.40m ³
10	2.25m	1.30m	0.30m	12.67m ³
8	2.75m	1.45m	0.30m	9.57m ³
14	3.15m	1.20m	0.30m	15.87m ³
7	2.80m	1.55m	0.30m	9.11m ³
12	2.25m	1.70m	0.30m	19.85m ³
16	2.75m	1.40m	0.30m	18.48m ³
11	3.20m	1.25m	0.30m	13.61m ³
8	2.70m	1.30m	0.30m	8.42m ³
6	2.65m	1.45m	0.30m	6.91m ³
Total =				128.93m ³

② Making up of Bays / should be

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B/E	B	2,01,137=00
$\frac{7}{8}$ Maintenance of CID walls (slab cut)					
02 NOS, wide TMBL-71					
			@ B 2243.59/mo-B		4487=00
$\frac{8(i)}{11(i)}$ cutting of branches of trees & shrubs					
03 NOS, wide TMBL-72					
			@ B 101264/mo-B		3058=00
$\frac{8(ii)}{11(ii)}$ cutting of shrubs for roadways					
13 NOS, wide TMBL-72					
			@ B 6224/mo-B		812=00

$\frac{8(iii)}{11(iii)}$ Trimming of grass & weeds					
31.00 m ² , wide TMBL-72					
			@ B 2.08/m ²		64=00
$\frac{8(ii)}{11(ii)}$ White washing of parapet wall of CID wall					
92.82 m ² , wide TMBL-72					
			@ B 15280/m ² -B		14662=00
			Total = B		2,07,540=00
Less 0.01% (rule)			@ B		21=00
					Rs 2,07,519=00

(Rupees Two Lakh, seven thousand five hundred & nineteen paise) only

Continuation

Handwritten signature
06/04/24
(A.E)