

## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- RWD, Jhaghpur	
Name of Block/Road :- Pmgsy Road to yadav Tol	
<b>A. For Road</b>	
1. Damage Location/Chainage :- 6 m, 350 m	
2. Damage Length :- 16.10 m	
3. Nature of Damage (Length Wise)	(i) Breach :- 16.10 m.
	(ii) Crust Damage :-
	(iii) Only Flank Damage :-
whether traffic fully/Partially obstructed :-	
4. Details of Restoration :-	
(i) Material Being Used in Restoration :- Brick rati	
(ii) Equipment/Tools Being Used in Restoration Works :- JCB & Tractor	
(iii) Restored Length	In open Area :- open
	In habitation Area :-
(iv) If Restoration work done in habitation Area give Reason :-	
<b>B. For Bridge (Size of Bridge/Culvert)</b>	
(1) Damage Location/Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttment/Wing Wall/Approach Road Damage) :-	
(5) Details of Restoration :-	
(i) Material Being Used in Restoration :-	
(ii) Equipment/Tools Being Used in Restoration Works :-	
(iii) Restored Length :-	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-	

Q. 14/10/24  
J.E.

  
**Executive Engineer**  
 Signature of Inspector  
 Rural Works Department  
 (Official Seal)