

2nd Year Maintenance.

74

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

Name of work:—Construction of road from PWD road to Ghoraghatta.

Under:- MMGSY.

Name of agency:—M/S. Chandra Bhushan Singh.

Agreement No.:—26 SBD/2013-14.

Date of start:—06.09.2013.

Date of Completion:—05.09.2014.

Date of actual completion:—15.05.2016.

Date of entry:—13.05.2018.

① Restoration of main cut

With soil & dlu

~~2018~~

$$31 \times 30.00 \times 1.00 \times 0.20 = 186.00 \text{ m}^3$$

$$1 \times 15.00 \times 1.00 \times 0.20 = 3.00$$

$$31 \times 30.00 \times 1.00 \times 0.20 = 186.00$$

$$1 \times 15.00 \times 1.00 \times 0.20 = 3.00$$

$$378.00 \text{ m}^3$$

② Maintenance of earthen

Shoulder (filling with

fresh selected soil)

$$38 \times 30.00 \times 0.90 = 1026.00 \text{ m}^3$$

$$1 \times 25.00 \times 0.90 = 22.50$$

$$38 \times 30.00 \times 0.90 = 1026.00$$

$$1 \times 25.00 \times 0.90 = 22.50$$

$$2097.00 \text{ m}^3$$

③ Maintenance of bituminous

Surface road. Repair of

potholes with cleaning

Surface by providing

Continuation

4.

6 Nos.

15/5/18

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST.</u>					
① Restoration of raincuts					
With soil - do - do					
V.P. 74	①		378.00m ²		
@ Rs. 282 = 71/m ²					Rs. 1,06,864.38
② Maintenance of earthen Shoulders (filling with fresh Selected Soil)					
V.P. 74	②		2097.00m ²		
@ Rs. 23 = 93/m ²					Rs. 50,181.21
③ Repair of pot holes with Cleaning Surface with tack coat, 20mm thick premix Carpet and Seal coat type B					
V.P. 75	③		127.075m ²		
127.075m ² @ Rs. 216 = 57/m ²					Rs. 27,520.63
④ Maintenance of Slab Culvert.					
V.P. 75	④		6 Nos.		
@ Rs. 774 = 52 each					Rs. 4647.12
					Rs. 1,89,213.34
less 5.51% as per agreement.					(-) Rs. 10,425.66
					Rs. 1,78,787.68
					Say Rs. 1,78,788.00
Belani 13.05.18 82 15/5/18 15/5/18					
Continuation					