

5th year maintenance

49

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: Karmaitka					
Kewatsa path to mark					
To/From					
2. Name of agency: Salsal Kumar					
misra					
3. Agreement No: 92/SB/2017-18					
4. Actual dt. of work: 31.08.2019					
— measurement as below —					
① Restoration of zeein					
cuts with soil as per					
Restoration of Rain cuts /					
Berms with soil as per					

1x 20.50 x 0.75 x 0.30 = 4.612	
2x 30.0 x 0.65 x 0.30 = 11.70	
1x 30.0 x 0.60 x 0.30 = 5.40	
3x 30.0 x 0.60 x 0.28 = 15.12	
2x 20.60 x 0.52 x 0.32 = 3.995	
1x 30.0 x 0.60 x 0.30 = 5.40	
2x 30.0 x 0.60 x 0.30 = 10.80	
3x 28.0 x 0.60 x 0.28 = 14.112	
	Qty = 71.1372
	Soyab = 71.0883

② making up of Berms /
shoulders, stripping excess
soil from the shoulders

Continuation
surfaces
1x 20.0 x 0.75 = 22.50 m²
1x 20.0 x 0.70 = 14.00 m²
C.O. Qty = 36.50 m²
P = 0.0

Continuation