

5th year maintainance

55

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

Name of road- Rasulpur malband

RA Premraj chowk

Se puzab sei parash

paswan ke gulcan se

to mahadali tole mainin

tole hole hue wazhoos

Agency- Pramod Kumar

Ag. no- 66/SBD/2019-20

Actual- D.O. comp. - 04/01/2020

date of measurement

① Restoration of drains

$$2 \times 3 \times 30.0 \times 0.25 \times 0.30 = 51.30$$

$$2 \times 2 \times 30.0 \times 0.15 \times 0.30 = 37.80$$

signs

1.4 h 10m vide m B Pro (57)

@ 1066-51/m 1536

(8/11) maintenance of 20m

2 km stone

0.346 km @ 772-32/m 267 =

(9/12) Cutting of branches
of trees

20 m @ 105-20/m 949 =

(10/13) cutting of shrubs

18 m vide m B Pro (57)

@ 6-47/m 117 =

(11/14) Trimming of grass

2025.00 m² @ 2-18/m² 4377 =

(12/15) white wash two
coats on parapet

20.64 m² vide m B Pro (57)

@ 17205/m² 460 =

381904 =

Less 10% as per agreed 38190 =

343714 =

Sub to 31/5/24 Continuation

UP
Sanjay 03/19/24
15/10/24