

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W:-	Middle School Bansi to				
	Selat Deri Achan Tak				
Agency:-	M/s Singh construction				
	L. Company.				
Agg No:-	55 S.B.D/2018-19				
Date of start:-	18/12/2018				
Actual Date of comp:-	15.12.2019				
Date of Entry:-	As below.				
	Measurement				
(1) Restoration of road culs					
with soil masonry - do -					
ch. sp.					
	12	8.0	0.9	0.3	25.920
	8	5.0	0.90	0.3	10.800
	10	4.0	0.9	0.3	10.80
	7	5.0	0.90	0.3	9.450
	9	6.0	0.90	0.3	14.580
	5	3.0	1.025	0.3	5.063
					= 76.613 M ³
(2) Maintenance of earthen					
shoulder - do - ch. sp.					
	12	10	0.90		108.00
	8	6.0	1.02		53.76
	10	6.0	1.025		67.50
	7	8.0	0.90		50.400
	9	8.0	0.90		64.80
	5	5.0	1.02		28.00
	7	6.0	1.25		52.500
Continuation					= 424.960 M ²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(4) P/L hat applied thru black compound					
Qty. vide TMB P/O - (78)					
260.00m ² @ Rs 770.48/m ² Rs = 206325.20					
(5) Repair of bitumen surface road do-					
Qty. vide TMB P/O - (78)					
157.38 m ² @ Rs 259.94/m ²					
					Rs = 39350.00
(6) Repair of lime pipe culvert do - fetch					
Qty. vide TMB P/O - (78)					
6 Nos. @ Rs 1132.27/each Rs = 6794.20					
(7) Repair of R.C. slab culvert do - fetch					
Qty. vide TMB P/O - (78)					
4.00 Nos. @ Rs 2338.06/each					
					Rs = 9352.00
(8) Repair of 200 mtr 2 km stone do - fetch					
Qty. vide TMB P/O - (79)					
1.30 km @ Rs 728.76/km Rs = 947.00					
					Rs = 328830.00
Sub Total					
JE					